Operational Experience, Improvements, and Performance of the CDF Run II Silicon Vertex Detector

T. Aaltonen^p, S. Behari^{q,l,*}, A. Boveia^{h,f}, B. Brau^{h,v}, G. Bolla^{ae}, C. Calancha^u, S. Carron^{l,ai}, S. Cihangir^l, M. Corbo^{ab}, D. Clark^c,

B. Di Ruzza^{l,d}, R. Eusebi^{l,aj}, J. P. Fernandez^u, J. C. Freeman^l,

J. E. Garcia^{ac,n}, M. Garcia-Sciveres^s, D. Glenzinski^l, O. González^u,

S. Grinstein^{o,b}, M. Hartz^{ad,ak}, M. Herndon^{q,am}, C. Hill^{h,z}, A. Hocker^l,

U. Husemann^{af,ao,r}, J. Incandela^h, C. Issever^{h,aa}, S. Jindariani^l, T. R. Junk^l

K. Knoepfel¹, J. D. Lewis¹, R. S. Lu^{a,t}, R. Martínez-Ballarín^u, M. Mathis^{q,an},

M. Mattson^{al}, P. Merkel^{l,ae}, L. Miller^o, A. Mitra^a, M. N. Mondragon^l,

R. Moore^{l,w}, J. R. Mumford^q, S. Nahn^{ao,x}, J. Nielsen^{s,i}, T. K. Nelson^{ai},

V. Pavlicek¹, J. Pursley^{q,y}, I. Redondo^u, R. Roser¹, K. Schultz¹, J. Spalding¹,

M. Stancari^l, M. Stanitzki^{ao,j}, D. Stuart^h, A. Sukhanov^{m,l}, R. Tesarek^l,

K. Treptow^l, R. Wallny^{g,k}, S. Worm^{ag,ah,e}

^aAcademia Sinica, Taipei, Taiwan 11529, Republic of China

^bInstitut de Fisica dAltes Energies, ICREA, Universitat Autonoma de Barcelona, E-08193,

Bellaterra (Barcelona), Spain

^cBrandeis University, Waltham, Massachusetts 02453

^dPhysics Department, Brookhaven National Laboratory, Upton, New York 11973

^eCERN, CH-1211 Geneva, Switzerland

^fEnrico Fermi Institute, University of Chicago, Chicago, Illinois 60637

^gUniversity of California, Los Angeles, California 90095

^hUniversity of California, Santa Barbara, California 93106

ⁱSanta Cruz Institute for Particle Physics, University of California, Santa Cruz, California 95064

^jDESY, Notkestr. 85, D-22603 Hamburg and Platanenallee 6, D-15738 Zeuthen, Germany

^kETH Institute for Particle Physics, Schafmattstrasse 20, 8093 Zurich, Switzerland

¹Fermi National Accelerator Laboratory, Batavia, Illinois 60510

^mUniversity of Florida, Gainesville, Florida 32611

ⁿUniversity of Geneva, CH-1211 Geneva 4, Switzerland

^oHarvard University, Cambridge, Massachusetts 02138

^pUniversity of Helsinki and Helsinki Institute of Physics, FIN-00014, Helsinki, Finland

^qThe Johns Hopkins University, Baltimore, Maryland 21218

^rInstitut für Experimentelle Kernphysik, Karlsruhe Institute of Technology, D-76131 Karlsruhe, Germany

^sErnest Orlando Lawrence Berkley National Laboratory, Berkley, California 94720

^tNational Taiwan University (NTU), Taipei, Taiwan

^uCentro de Investigaciones Energeticas Medioambientales y Tecnologicas, E-28040 Madrid, Spain

^vDepartment of Physics, University of Massachusetts, Amherst MA

^wMassachusetts General Hospital, Harvard Medical School, Boston, Massachusetts 02114 ^xMassachusetts Institute of Technology, Cambridge, Massachusetts 02139

⁹Brigham and Women's Hospital, Harvard Medical School, Boston, Massachusetts 02115

^z The Ohio State University, Columbus, Ohio 43210

^{aa} University of Oxford, Oxford OX1 3RH, United Kingdom

Preprint submitted to Nuclear Instrumentation Methods A

[☆]FERMILAB-PUB-13-015-E

^{*}Corresponding author

Email address: behari@fnal.gov (S. Behari)

^{ab}LPNHE, Universite Pierre et Marie Curie/IN2P3-CNRS, UMR7585, Paris, F-75252

France

^{ac} Istituto Nazionale di Fisica Nucleare Pisa, Universities of Pisa, Siena and Scuola Normale

Superiore, I-56127 Pisa, Italy

^{ad} University of Pittsburgh, Pittsburgh, Pennsylvania 15260

^{ae}Purdue University, West Lafayette, Indiana 47907

 $^{af}University$ of Rochester, Rochester, New York 14627

^{ag}Rutgers University, Piscataway, New Jersey 08855

^{ah}Rutherford Appleton Laboratory, Science and Technology Facilities Council, Harwell

Science and Innovation Campus, Didcot OX11 0QX, United Kingdom

^{ai}SLAC National Accelerator Laboratory, Menlo Park, California 94025

^{aj} Texas A&M University, College Station, Texas 77843

 $^{ak}\mathit{University}$ of Toronto, Toronto, Ontario M5S 1A7, Canada

^{al} Wayne State University, Detroit, Michigan 48202

^{am}University of Wisconsin, Madison, Wisconsin 53706

an College of William & Mary, Williamsburg, Virginia 23187

^{ao} Yale University, New Haven, Connecticut 06520

Abstract

The Collider Detector at Fermilab (CDF) pursues a broad physics program at Fermilab's Tevatron collider. Between Run II commissioning in early 2001 and the end of operations in September 2011, the Tevatron delivered 12 fb^{-1} of integrated luminosity of $p\bar{p}$ collisions at $\sqrt{s} = 1.96$ TeV. The physics at CDF includes precise measurements of the masses of the top quark and Wboson, measurement of CP violation and B_s mixing, and searches for Higgs bosons and new physics signatures, all of which require heavy flavor tagging with large charged particle tracking acceptance. To realize these goals, in 2001 CDF installed eight layers of silicon microstrip detectors around its interaction region. These detectors were designed for 2–5 years of operation, radiation doses up to 2 Mrad (0.02 Gy), and were expected to be replaced in 2004. The sensors were not replaced, and the Tevatron run was extended for several years beyond its design, exposing the sensors and electronics to much higher radiation doses than anticipated. In this paper we describe the operational challenges encountered over the past 10 years of running the CDF silicon detectors, the preventive measures undertaken, and the improvements made along the way to ensure their optimal performance for collecting high quality physics data. In addition, we describe the quantities and methods used to monitor radiation damage in the sensors for optimal performance and summarize the detector performance quantities important to CDF's physics program, including vertex resolution, heavy flavor tagging, and silicon vertex trigger performance.

Keywords: Silicon, Vertex Detector, CDF, Tevatron Run II, Detector Operations

1 1. Introduction

The Tevatron collider at the Fermi National Accelerator Laboratory (FNAL)
 collided proton and antiproton beams at a center-of-mass energy of 1.96 TeV.
 The collisions happened at two interaction points where multipurpose detectors
 Collider Detector at Fermilab (CDF II) and D0, were positioned.

The CDF II detector [1] was a general purpose detector with a cylindrical geometry. The innermost part of the detector consisted of charged-particle tracking detectors, shown in Fig. 1, which were located inside a superconducting solenoidal magnet which provided a highly uniform 1.4 T magnetic field oriented parallel to the beam axis. Calorimeters and muon systems outside the solenoid provided lepton identification and momentum measurement as well as jet energy measurements. The tracking detectors and calorimeters together provided identification of jets from heavy (charm and bottom) quarks.

The inner component of the tracking system was a series of silicon microstrip detectors that constituted the CDF silicon detector. Beyond the silicon detector lay the Central Outer Tracker (COT), an open-cell drift chamber. Together with the additional constraints coming from the position of the primary vertex, the COT and Silicon Detector provided a resolution on the track momentum transverse to the beam direction, p_T , of $\sigma(p_T)/p_T = 0.15\% \cdot p_T/(\text{GeV}/c)$.



Figure 1: Isometric view of the entire CDF II detector (left), and schematic layout of the CDF II tracking system (right).

CDF II used a cylindrical coordinate system with the z axis oriented along 20 the proton beam direction and azimuthal angle ϕ measured around the beam 21 axis. The polar angle θ was measured with respect to the positive z (proton-22 beam) direction and was used to define the pseudorapidity $\eta \equiv -\ln(\tan(\theta/2))$. 23 The physics program of Run II at the Tevatron includes precision measure-24 ments of the mass of the top quark and W boson; bottom and charm physics, 25 including the determination of the B_s and D^0 mixing parameters; studies of the 26 strong interaction (jet multiplicities, diffractive physics, etc.); and searches for 27 objects and phenomena as varied as the Higgs boson, supersymmetric particles, 28 hidden space-time dimensions, and quark substructure [2–5]. All these measure-29 ments benefit from a high-resolution tracking detector and many rely heavily on 30

the efficient identification of heavy quarks by detection of displaced secondary vertices, and are enhanced by the capability to trigger on tracks originating away from the beam.

The CDF silicon detector was designed to withstand radiation doses up to 34 $2 \,\mathrm{MRad} \,(0.02 \,\mathrm{Gv})$, the dose expected during the first 2–5 years of CDF opera-35 tions, with an upgrade planned in 2004 [6]. However, the upgrade project was 36 canceled in 2003, and Run II was later extended into late 2011, with total deliv-37 ered integrated luminosity of 12 fb^{-1} . Several preventive measures were taken to 38 keep the original silicon detector operational and maintain its performance. The 39 most important of these was the decrease in the operating temperature of the 40 detector, which reduced the impact of chronic radiation exposure (Section 5). 41 Steps were also taken to minimize thermal cycles, damage from resonances of 42 wire bonds (Section 3.6), and instabilities and sudden loss of the Tevatron beams 43 (Section 6). 44

Issues arising from radiation damage of the sensors, aging infrastructure, 45 and electronics were addressed continuously in addition to the basic challenges 46 posed by the inaccessibility of the detector volume and large number of readout 47 channels (approximately 722,000). The operational challenges, improvements 48 to, and the performance of the CDF silicon detector are presented in this paper. 49 This paper is organized as follows: Section 2 provides a general description 50 of the detector, Section 3 gives an overview of the data acquisition, the trigger, 51 and the interface between them. Section 4 describes the power supplies and the 52 operational experience with them and response to their failures, Section 5 de-53 tails the design, history, and response to failures in the cooling system, Section 6 54 gives a review of particle beam incidents, and response to them. Section 7 de-55 tails the readout calibration, Section 8 is dedicated to the routine monitoring 56 and operations support systems, Section 9 describes the response of the CDF 57 silicon detector to accumulated radiation doses, Section 10 details the perfor-58 mance of the silicon detector and the displaced vertex trigger, and Section 11 59 gives a summary. As well as new results, this paper compiles final results on 60 material dispersed in several conference proceedings produced over the years by 61 the members of operations team [7-12]. 62

63 2. Detector Description

The CDF silicon detector system consisted of three sub-detectors, all with 64 barrel geometry: Layer 00 (L00) [8, 13], the Silicon Vertex detector (SVX-65 II) [14, 15] and the Intermediate Silicon Layers (ISL) [16]. Unless otherwise 66 stated, detector refers to the CDF silicon detector. The design of the system was 67 driven by the goal of providing excellent spatial resolution in the measurement of 68 charged-particle tracks. These measurements were crucial for the reconstruction 69 of the displaced secondary vertices and therefore, identification of events with 70 bottom-quarks. Figures 2 and 3 present the schematic layout of the CDF silicon 71 detector, and Table 1 summarizes some of the basic parameters. The design 72 had eight silicon layers to provide tracking which is robust against failure or 73 degradation of individual components. 74



Figure 2: Schematic layout of the CDF silicon detectors showing x-y ($r-\phi$, left) and y-z (r-z, right) views. Note that the z axis is compressed for illustration purposes.

The basic structural unit of a sub-detector was a *ladder*, which consisted of 75 several silicon microstrip sensors (3 sensors for L00 ladders, 4 in SVX-II ladders 76 and 6 in ISL ladders) with strip width and multiplicity depending on the *layer*, 77 or distance from the beam pipe. The sensors were made from high-resistivity 78 n-type silicon with a nominal thickness of 300 μ m. Sensors in L00 were single-79 sided, providing $r - \phi$ information, while sensors in the other layers were double-80 sided, providing both $r-\phi$ and r-z information. The sensors in SVX-II layers 0, 81 1, and 3 used double-metal readout for a 90° strips on the r-z side. The other 82 double-sided layers used small-angle stereo strips. 83

The readout was carried out through aluminum strips AC coupled to the 84 implant strips, which are of p-type for the $r-\phi$ and n-type for the r-z side. A full 85 ladder was read out from both ends through SVX3D readout chips (described 86 in Section 3.3.1) mounted on electrical hybrids. These hybrids were located 87 outside (for L00) or inside (for SVX-II and ISL ladders) of the tracking volume. 88 A circuit board called the *portcard* was located at the periphery of each support 89 structure or bulkhead and formed an interface with the hybrids and readout 90 chips with the rest of the data acquisition system (Section 3). 91

Layer 00 was a single-sided silicon microstrip detector whose sensors could 92 be biased to higher voltages than the double-sided sensors. It was mounted on 93 a carbon fiber support structure which was in turn mounted directly on the 94 beam pipe, and had an inner radius of 1.15 cm and outer radius of 2.1 cm. 95 Its main purpose was to improve the track impact parameter resolution which 96 was otherwise limited by multiple scattering in the additional material of the 97 SVX-II readout and cooling infrastructure; a secondary purpose was to prolong 98 CDF silicon detector lifetime by providing a backup to SVX-II layer-0. Layer 99 00 consisted of one layer and had 72 ladders with 13,000 readout channels in 100 total. 101



Figure 3: Dimensions, in cm, of the CDF silicon detector system. Shown are x-y and y-z views. In the y-z view, each square corresponds to one sensor and each subdetector has been displaced along the y-axis for illustration purposes.

The SVX-II detector was built in three cylindrical barrels each 29 cm long. 102 Each barrel contained five layers of double-sided silicon microstrips placed along 103 the beam axis, with radial coverage from 2.5 to 10.7 cm. Carbon fiber re-104 inforced Rohacell foam [17] provided support to the ladders, and beryllium 105 bulkheads provided additional support and alignment on each end. Therefore 106 the detector consisted of six bulkheads (z-segmentation), each with 12 wedges 107 (ϕ -segmentation) consisting of 5 layers (r-segmentation). In total, it had 360 108 ladders with 405,504 channels in the system. One side of each microstrip sensor 109 provided tracking information in the $r - \phi$ plane, with strips oriented parallel to 110 the beam direction, while the other side had strips oriented either perpendicular 111 to the beam axis, providing 90° information, or at an angle of $\pm 1.2^{\circ}$ with respect 112 to the beam axis, providing small-angle stereo information. Three of the five 113 SVX-II layers had 90° sensors, while the remaining two layers had small-angle 114 stereo strips, as detailed in Table 1. The readout chips and electric hybrids were 115 mounted on the surface of the SVX-II silicon sensors. SVX-II was read out in a 116 strict ϕ -wedge geometry in order to feed the secondary vertex trigger, described 117 in Section 3.1.1. 118

The ISL was located between SVX-II and the COT drift chamber. It con-119 sisted of one central $(|\eta| < 1)$ layer of silicon at a radial position of 22 cm and 120 two forward $(1 < |\eta| < 2)$ layers at 20 cm and 28 cm. Mechanical support for 121 the ladders was provided by carbon fiber rings. ISL had 148 double-sided lad-122 ders of 55 cm length each with a total of 303,104 channels. An ISL ladder was 123 composed of three microstrip sensors bonded together. Like SVX-II, one side of 124 each sensor provided tracking information in the $r-\phi$ plane while the other side 125 provided tracking information in the r-z plane with $\pm 1.2^{\circ}$ stereo angle. Also 126 like SVX-II, the readout chip hybrids were mounted on the sensors. 127

Figure 4 gives a historical account versus time (left) and integrated luminos-

Name	Radius (cm)	Readout	Manufacturer
L00 (narrow)	1.35	r - ϕ	SGS Thomson, Micron
L00 (wide)	1.62	r - ϕ	Hamamatsu
SVX L0	2.54	r - ϕ , r - z	Hamamatsu
SVX L1	4.12	r - ϕ , r - z	Hamamatsu
SVX L2	6.52	$r-\phi, +1.2^{\circ}$	Micron
SVX L3	8.22	r - ϕ , r - z	Hamamatsu
SVX L4	10.10	r - ϕ ,-1.2°	Micron
ISL L6 Central	22.00	r - ϕ ,1.2°	Hamamatsu
ISL L6 Fwd/Bwd	20.00	r - ϕ ,1.2°	Hamamatsu
ISL L7 Fwd/Bwd	28.00	r - ϕ ,1.2°	Micron

Table 1: Summary of L00, SVX-II and ISL basic parameters.

¹²⁹ ity (right) of the fraction of detector ladders included in data taking since start of commissioning in 2001. Aside from variation during the start-up period,



Figure 4: Fraction of ladders which were powered (black), considered good (green) and bad (red) versus time (left) and versus integrated luminosity (right). A ladder is considered good if it has less than 1% digital errors. Also shown is the average digital error rate (pink). The actual fraction of good ladders is larger as it does not included ladders whose digital errors are corrected by the offline reconstruction software.

130

stable detector operation is observed over the long term data taking period.
The rate of corruption in data transmission out of the detector (referred to as
"digital errors") rises with time. Some of this corruption was recovered with offline processing by using knowledge of the data structure to identify and correct
erroneous bits.

¹³⁶ 3. The Silicon Detector Data Acquisition System

The data acquisition (DAQ) system of the silicon detector was responsible for 137 reading out and digitizing the charge collected by the 722,432 silicon strips. The 138 DAQ worked in coordination with the CDF trigger system that selected events 139 (proton-antiproton collisions) of interest [1]. The DAQ system was comprised 140 of radiation-hard readout ASICs mounted on the detector, feeding optical data 141 links and a chain of VME boards that coordinated the DAQ process and that 142 collated and processed the data. The unique feature of the DAQ system was 143 the integration of the silicon detector with the secondary vertex trigger (SVT) 144 which had never been attempted at a hadron collider. 145

The first half of this section (Sections 3.1- 3.4) describes the CDF DAQ and then details the components of the silicon detector DAQ. The second half (Sections 3.5.1- 3.9) describes the commissioning and operations experience, which includes the unexpected behaviors of the SVX3D chip, noise from L00, and effect of radiation on the DAQ.

151 3.1. CDF Timing and Trigger

The CDF trigger and DAQ systems were synchronized to the Tevatron beams. The Tevatron divided the proton and antiproton beams into 3 trains, separated by $1.4 \,\mu$ s, and each train was composed of 12 bunches separated by 396 ns. In total there were 36 bunches of protons and antiprotons. It took 21 μ s to complete one revolution of the Tevatron. The orbits of the proton and antiproton beams were set to collide every 396 ns¹ at the two points where the CDF and D0 detectors were located.

The CDF clock signals were derived from the Tevatron clock system. The 159 most fundamental clock was derived from the 53 MHz Tevatron radio frequency 160 (RF) system² The Tevatron also sent a signal corresponding to the first proton 161 bunch, with a period of $21 \,\mu s$ (1113 Tevatron RF clock periods) in phase with 162 the RF clock. Further details on the Tevatron beam structure and clocks are 163 available in [18] and references therein. The fundamental CDF clock was derived 164 by dividing the Tevatron RF clock by 7, which gave a period of 132 ns and phased 165 with the first proton bunch clock. Additional clock signals were derived for valid 166 bunch crossings and the gaps between trains. 167

At a hadron collider, only a small fraction of events are from interesting physics processes. The CDF trigger was responsible for identifying these interesting events in real time. CDF employed a three-level trigger system, where each level used more refined information than the previous level to select events. The first level (L1) ran synchronously with the CDF clock and had a fixed latency of 5.5 μ s. It reduced the event rate from 1.7 MHz to less than 35 kHz, and was implemented with custom hardware [1]. When events were selected by

 $^{^1{\}rm The}$ Tevatron proton-antiproton collision rate was intended to be upgraded to $132\,{\rm ns},$ but this change was not implemented.

²The central Tevatron RF system fed the Tevatron's accelerating RF cavities.

L1, the data for non-silicon detectors were stored in one of four buffers, pending 175 processing by the second level (L2). L2 was an asynchronous trigger, comprised 176 of dedicated hardware and software, that selected a subset of the L1 triggered 177 events. It reduced the peak rate of accepted events to $\sim 800 \,\text{Hz}$. The third level 178 (L3) was a software trigger that ran a fast version of the offline event recon-179 struction on a computer farm using all data from the CDF detector. It selected 180 a subset of L2 triggered events for permanent storage at a rate of ~ 150 Hz. 181 Overall, the CDF trigger selected ~ 1 in 11,000 collisions for permanent storage. 182

183 3.1.1. SVT

A unique feature of the CDF's L2 trigger was the ability to select events with a displaced vertex which were characteristic of bottom quark hadron (*b*hadron) decays. This method of selecting hadronic *b*-decay events was more efficient than previous leptonic triggers that relied on the rarer semi-leptonic *b*quark decay. This displaced vertex trigger, known as the Silicon Vertex Trigger (SVT), significantly increased CDF's yield of *b*-hadrons for analysis.

The SVT used data from the CDF silicon detector and COT to perform 190 precision tracking quickly. Tracks were found by combining information from 191 the COT-based extremely fast tracker (XFT) [19] and SVX-II axial layers to 192 patterns stored in look-up tables. The resulting tracks in the $r-\phi$ plane were 193 used to calculate the 2D distance (L_{xy}) of a track pair intersection from the 194 primary vertex. A key development of the SVT hardware was the custom chip-195 based pattern recognition (associative memory). CDF was the first detector at 196 a hadron collider to implement a displaced vertex trigger. Further information 197 on the SVT can be found in [20-22] and references therein. The demands of 198 SVT to reconstruct tracks and identify tracks displaced from the interaction 199 point drove the SVX-II design and led to the wedge and barrel layout, the tight 200 construction alignment tolerances, and the SVX-II DAQ design that is discussed 201 in this section. 202

203 3.2. CDF Silicon DAQ architecture

SVX-II was designed for SVT, which required a specialized DAQ system to 204 provide silicon strip data in 20-40 μ s. The ISL and L00 that came as extensions 205 to the CDF silicon detector project inherited the SVX-II DAQ. Thus the SVX-206 II DAQ defined the entire CDF silicon detector DAQ. SVT demanded SVX-II 201 provide data after every L1A. This required deadtimeless readout to guarantee 208 silicon data was always available. Also, to reduce the time to deliver and pro-209 cess the data, only information from silicon strips which collected a significant 210 amount of charge relative to the nominal noise signal was propagated to SVT. 211 Therefore the silicon readout volume, and thus readout time, was driven by the 212 underlying physics processes that drove the occupancy of the detector. It was 213 only by meeting these design challenges that allowed the combination of SVX-II 214 and SVT to be integrated into the CDF trigger. 215

Figure 5 shows a schematic diagram of the silicon DAQ system. The process was coordinated by a central controller that interfaced with the trigger

system, broadcasted commands to the individual ladders, and controlled data 218 flow through feedback signals from the VME readout buffers. The digitized data 219 from each ladder was transferred in parallel to the allocated readout buffer. The 220 data were buffered until a L2 decision arrived and was either transmitted to L3 221 or discarded. The Silicon DAQ was synchronized to the CDF clock. The elec-222 tronics were divided into an on-detector part, mounted directly on the silicon 223 detector, and an off-detector part, located in VME racks in the CDF collision 224 hall and in the CDF counting room (Fig. 5). 225



Figure 5: A schematic diagram of the silicon detector DAQ system. The SVX-II wedge and portcard, at the top half of the figure, were known together as the on-detector electronics as they were located directly on the silicon detector. The components, in the lower half of the figure, were known as the off-detector electronics. The FIB and FIB fanout were located in the CDF collision hall. The VRB, VRB fanout and SRC were in the CDF counting room which was located above the CDF collision hall. ISL and L00 DAQ were identical except the SVX-II wedge was substituted with a ISL and L00 wedge, respectively.

226 3.3. On-detector Electronics

The on-detector electronics were responsible for acquiring and digitizing the charge from the silicon strips and then transmitting the data to the off-detector electronics. The on-detector electronics consisted of the SVX3D readout chip, the portcard, and DOIM optical data links that are described below.

231 3.3.1. The SVX3D Readout Chip

The SVX3D ASIC was responsible for acquiring charge from the silicon strips 232 and digitizing them. It was a custom, radiation-hard, deadtimeless, 128-channel 233 device [23, 24], capable of recording charge simultaneously from all 128 channels 234 every 132 ns and had an 8-bit wide output running at 53 MHz. All 128 chan-235 nels were digitized simultaneously using an 8-bit grey-coded modified Wilkinson 236 type analog-to-digital converter (ADC) that included event-by-event dynamic 237 pedestal subtraction (DPS). With DPS, it was no longer necessary to read out 238 every strip for an offline pedestal subtraction. Therefore the SVX3D could 239 implement data reduction logic (sparsification) to remove channels that were 240 below a set threshold to reduce further the readout time. In this way, the read-241 out time was dictated by the occupancy of the silicon detector. The SVX3D's 242 deadtimeless operation, DPS, and sparsification were essential for SVT. 243

The SVX3D was manufactured using the Honeywell CMOS 0.8 μ m radiationhard process. From irradiations up to 4 MRad with ⁶⁰Co sources and 15 MRad with a 55 MeV proton source, the chip noise in the innermost layer of SVX was expected to increase by 17% after 8 fb⁻¹ (3.1 MRad) [25].

The operations of the chip were divided into an analog front end (FE) and a digital back end (BE). The FE was responsible for acquiring charge from the silicon strips and buffering them into a circular analog pipeline. The BE digitized the charge from the pipeline and any channels above a programmed threshold were sent to a readout FIFO. The FE and BE were driven independently by the CDF clock and Tevatron RF clock, respectively, which ensured the deadtimeless operation.

The chip operation began with an initialization phase which set various operational parameters such as the signal polarity, chip identification number (chip ID), and readout mode. After the initialization phase, the FE changed to the acquisition mode, and the BE alternated between digitization and readout, until a new initialization was performed.

Each FE channel consisted of a charge integrator coupled to a 47 stage 260 circular analog capacitor pipeline; 42 pipeline cells were allocated for the L1 261 latency, four for L2 buffers, and one reserved to measure the pipeline pedestal. 262 Every CDF clock cycle, the FE charge integrator acquired charge from the silicon 263 strips and transferred it to an empty cell in the analog pipeline. Whenever a 264 L1 decision to keep an event arrived, the appropriate pipeline cell was marked 265 and skipped over until it was digitized. Under normal operations, up to four 266 pipeline cells could be marked. 267

A marked analog pipeline cell (capacitor) was digitized by the BE. The voltage across the marked pipeline capacitor, subsequently referred to as the *strip*

voltage, went to the input of a comparator. The other input of the compara-270 tor was a voltage ramp shared by each channel's comparator. At the start of 271 digitization, the common voltage ramp started and an 8-bit grev-coded counter 272 started to increment. A channel's comparator changed state as soon as the volt-273 age ramp was larger than its strip voltage, which triggered a latch to store the 274 current value of the 8-bit counter. Therefore channels with smaller strip volt-275 ages would trigger their latches earlier. The common pedestal subtraction was 276 implemented by delaying the counter until the first 33 comparators had changed 277 state. The choice of 33 channels came from a study to optimize pedestal removal 278 with signal efficiency. DPS implicitly assumes a constant chip-wide pedestal³ 279 and insulates the strip charge measurement from environmental noise. 280

The SVX3D implemented three modes of data reduction: read out of strips above a set threshold (*sparse*), sparse strips and adjacent below-threshold strips (*nearest neighbor, NN*), and no data reduction (*read-all*). Sparse mode had the smallest data volume and therefore smallest read out time but NN was chosen as the additional information proved useful for correcting single bit errors. Except in the read all mode, the data volume was driven by the underlying physics that drove the occupancy of the silicon strips.

Multiple chips were chained together to read out a single silicon sensor; two 288 for the innermost (narrowest) layer and up to 16 for the outermost (widest) 289 layer. Chip initialization and commands were transferred serially from the first 290 chip in the chain to the last chip in the chain. The first strip of the first chip 291 and last strip of the last chip in the chip chain were always read. Data from 292 each chip in the chip chain were transmitted one-by-one on a common data bus. 293 The data from each chip included the chip ID and the SVX3D channel number 294 of each read strip. There were 5644 SVX3D readout chips in the CDF silicon 295 detector which dissipated approximately 3 kW of power, thus active cooling was 296 essential for stable operations (Section 5). 297

298 3.3.2. Portcard

The portcard was the interface between the on-detector and off-detector 299 electronics. It relayed SVX3D commands and trigger signals from the DAQ 300 boards and passed on power to bias the silicon sensors and chip chains from 301 the power supplies (Section 4). Data from the chips chains passed through the 302 portcard onto the optical data links (DOIMs) (Section 3.3.3). As the portcards 303 were located within the silicon detector, they were designed to have low mass to 304 minimize the radiation length, to with stand radiation doses of up to $\sim 200 \, \mathrm{kRad}$ 305 $(\sim 10 \,\mathrm{fb}^{-1})$, and with high heat transfer capability [26]. 306

307 3.3.3. Optical data link: DOIM

The Dense Optical Interface Module (DOIM) was the optical data link used to transmit data from a chip chain to the off-detector electronics [9]. Each

 $^{^3\}mathrm{This}$ assumption was not true for L00 and DPS was turned off for L00 readout (Section 3.7).

DOIM had a transmitter unit (TX) located on the Portcard and a receiver unit (RX) in an off-detector VME-transition module (Fig. 5). The TX and RX were connected by optical fibers. Each DOIM was capable of transmitting 8-bit wide data at 53 MHz with an error rate of less than 1 in 10¹² words.

The DOIM TX housed twelve 1550 nm InGaAsP edge emitting lasers in a single package. Only 9 of the 12 were used: 8 to transmit data and one as a data-strobe. The DOIM RX was a InGaAsP/InP PIN diode array. It received the optical signal from the TX and converted it back to an electrical signal. The DOIM TX was tested for radiation hardness with 30 MeV, 63 MeV, and 200 MeV protons with radiation doses up to 2 MRad. The light degradation was measured to be 10% after 200 kRads [27].

321 3.4. Off-detector Electronics

The off-detector electronics were responsible for coordinating the silicon DAQ process as well as processing and packaging the digitized silicon strip data for the SVT and the CDF DAQ.

The off-detector electronics were housed in eighteen 9U VME crates using VME64 [28]. Of these eighteen crates, eight were located in the CDF collision hall close to the CDF detector, while the other ten were located in a counting room in the CDF assembly building (Fig. 5). The main difference between the two sets crates was the use of two different custom J3 backplanes to accommodate different types of boards. All together, there were 164 VME boards.

Because the data from the SVX3D chip chains were sparsified, the first strip of the first chip and last strip of the last chip of the chip chain were always reported in order to identify the start and end, respectively, of the chip chain data stream. The off-detector electronics appended its own unique header to these data. The combination of the header, chip ID, and SVX3D channel encoded the unique location within the silicon detector of each digitized charge.

337 3.4.1. Silicon Readout Controller (SRC)

The SRC was the master controller of the silicon detector DAQ and also 338 acted as the interface to the CDF DAQ and trigger systems. The SRC was 339 housed in a rack in the CDF counting room, which was also shared with the VME 340 readout buffers (VRB), and received the clock and the beam structure from the 341 central CDF clock fanout. It communicated with the Trigger Supervisor (TS), 342 which was the central CDF trigger processor. The SRC also provided the central 343 clock to the entire CDF silicon detector, which was kept in sync with the CDF 344 clock using a phase locked loop (PLL). The SRC commands, clock, and trigger 345 signals were transmitted by the SRC via a Transition Module (SRCTM) to the 346 Fiber Interface Board (FIB) crates in the CDF collision hall using a GLINK [29] 347 optical link running at 53 MHz. 348

The Silicon DAQ was originally designed to be driven by a single SRC. However, the need to read out all channels of L00 every event (Section 3.7) required two SRCs, one to drive SVX-II and another to drive ISL and L00 (Section 3.7.1). Implementation of the second SRC also helped mitigate the *wirebond resonance* problem (Section 3.6).

354 3.4.2. Fiber Interface Board (FIB)

The Fiber Interface boards (FIB) were housed in eight crates located in the 355 four corners of the CDF collision hall. SVX-II and ISL/L00 had four FIB crates 356 each. The signals from the SRC were received by a FIB Fanout (FFO) board 357 in each FIB crate and distributed to the FIBs in its crate via a custom J3 358 backplane. Each FIB communicated with two portcards via a FIB Transition 359 Module (FTM) on the backside of the FIB crate. It converted the high-level 360 SRC commands into a sequence of instructions suitable for the SVX3D chip 361 chains, which were sent with clock and trigger signals to the two portcards. 362 The FTMs also housed the DOIM RX that received the digitized SVX3D data. 363 which were passed to the FIB. The FIB formatted the data stream, appended 364 its own unique header, and sent the data on four GLINKs to the VME Readout 365 Buffers (VRB) with a copy sent to the SVT through optical splitters. 366

367 3.4.3. VME Readout Buffer (VRB)

The VME Readout Buffers (VRB) were located in the VRB crates in the CDF counting room. Two VRB crates also housed the two SRCs. The VRB buffered the data from the FIBs until a L2 decision was made by the CDF trigger system, upon which the event was moved to the output buffer and was collected by the Event Building system using the VME Bus. The communication between the VRBs and the SRC was handled by the VRB fanout system, which enabled the SRC to manage the buffer provided by the VRBs.

The data from each VRB crate were transferred in parallel to the event 375 builder, which combined segments from the crates into an event record which 376 was then passed to L3. The SVX-II had 6 VRB crates that corresponded to the 377 6 SVX-II bulkheads. The ISL and L00 originally had two and one VRB crates, 378 respectively. To cope with high instantaneous luminosity (above $10^{32} \ cm^{-2} s^{-1}$), 379 it was necessary to reduce the size of the data segments arriving from the VRB 380 crates. In 2006, the ISL and L00 VRB crates were mixed and an additional 381 VRB crate was added (Section 3.7.2). 382

383 3.5. DAQ Commissioning

Prior to installation, the VME based hardware and onboard detector elec-384 tronics were thoroughly tested through the use of test stands and data emula-385 tion at various levels to verify the functionality and robustness of these systems. 386 However, due to time constraints, there was limited ability to test the two sys-387 tems together after installation. Together with the unforeseen consequences of 388 the environment in the collision hall, this led to several problems emerging in the 389 course of the first few years of operation that required immediate attention to 390 alleviate data corruption and potential damage to the detector. The wirebond 391 resonance and L00 noise problems were severe and are described separately in 392 sections 3.6 and 3.7 respectively. It took from 2001 to 2003 to fully commission 393 the silicon detector. 394

395 3.5.1. SVX3D Commissioning

The SVX3D chip was thoroughly tested during its development. But a number of unexpected behaviors, listed below, were encountered during commissioning. The chip would latch to a state where the chip current increased until it exceeded the power supply safety limit and forced a power supply shut down (trip). These behaviors were circumvented by modifying the SRC, VRB and FIB firmware.

Abort Digitize. The SVX3D chip had a feature to abort digitization before
completion if L2 had already rejected the event. However this feature made
the chip enter the high current state and trip. The SRC and FIB firmware
were modified to allow the SVX3D chip to always complete digitization which
stopped these failures.

Fifth L1 accept. The SVX3D chip could accommodate up to four L1A signals
without releasing a cell in the analog pipeline (Section 3.3.1). If a fifth L1A
arrived before a pipeline cell was released, the chip would transition to either
read-all mode or suppress all readout. The SRC firmware kept track of the
number of unreleased pipeline cells, and was modified not to send the fifth L1A
to the chips, and instead to send an error signal back to the CDF DAQ. This
error signal forced a silicon CDF DAQ reset and re-synchronization.

Keep-Alive. At least every 270 μ s, a command had to be sent to the chip chains 414 to prevent chips from entering the high current state and tripping. The SRC 415 firmware was updated to send these keep alive signals every $270 \,\mu s$ in the absence 416 of any commands. But the SRC state machine was driven by the CDF clock 417 and any glitches or interruptions of this clock would also delay or interrupt 418 the delivery of these keep-alive signals, which would result in large portions of 419 the chips tripping off. Given the sensitivity of the silicon detector to any clock 420 glitches, administrative procedures were implemented requiring permission from 421 either the CDF silicon detector project leader or the head of CDF detector 422 operations before work was done on on the CDF clock or Tevatron clock. 423

AVDD2 Errors. There was a class of unrecoverable failures that affected 6% 424 of the SVX3D chips and could be reproduced only by disabling one of SVX3D's 425 analog voltage lines (AVDD2). The observed symptoms were loss of commu-426 nication with the FE, an increase in the SVX3D's BE current, and loss of 427 communication to chips beyond the affected chip. This class of failure typically 428 occurred after a beam incident (Section 6) or a large temperature change, such 429 as a cooling system failure. This type of failure became infrequent after 2003 430 (Fig. 7 and 8) when operation procedures during shutdowns were changed to 431 minimize thermal cycles, coincident with a sharp decline in the frequency and 432 severity of beam incidents. 433

434 3.5.2. DAQ Board Enhancements

commissioning of the silicon detector, the SRC, VRB and FIB firmware were
 extended to circumvent the unexpected behaviors of the SVX3D readout chip,

which are documented in section 3.5.1. In addition, minor problems appeared
when the off-detector and on-detector components of the system were integrated.
A few of these issues are described in detail to illustrate the type of problems
encountered and solutions implemented.

Data was lost due to failures in the transmission of the clock signal from 441 the FIB/FTM to the portcard. Electronic components on the fiber interface 442 input of the FIB were replaced to increase the tolerance of varying duty cycles 443 on a signal that carried the clock information. The clock rate was known, and 444 failures in the transmission of its signal were overcome by providing an identical 445 backup clock signal. The firmware was also updated to increase the allowed 446 width of the front-end clock from about 28 ns to about 34 ns in order to avoid 447 the loss of charge collection due to inadequate integration time. 448

As the readout was data driven with no fixed length, the FIB used the last channel of the last chip in the chain to identify the end of a chip chain's data stream. Failure to detect this, which could be caused by the chip, DOIM, or FIB error, could potentially make the FIB wait for an indefinite amount of time. A timeout was added to the FIB to terminate readout and append an error code to the data stream.

⁴⁵⁵ Data were also initially lost to a race condition in the data concatenation ⁴⁵⁶ algorithm at the VRB level. This condition shifted every other 4 bits in the ⁴⁵⁷ data stream by 8 bits, leading to data corruption and the loss of events at the ⁴⁵⁸ 1% level. Once the systematic shift was distinguished from random corruption, ⁴⁵⁹ the VRB firmware was modified to eliminate this source of data loss.

460 3.6. Wirebond Resonance: Spontaneous loss of r-z sides in the double-sided 461 ladders

Shortly after the beginning of data taking operations in 2002, 4% of the 462 r-z side of SVX-II ladders were spontaneously lost during operations. In the 463 SVX-II, the $r-\phi$ and r-z side hybrids of the ladders were connected with a set 464 of wire bonds, known as the *jumper*. The jumper was perpendicular to the 465 1.4 T magnetic field produced by the CDF solenoid (Section 1). On every 466 readout sequence of the chips, a varying current flowed through the jumpers, 467 which resulted in a Lorentz force that induced a kick on the jumpers. This 468 process usually did not lead to a resonant condition, as the readout commands 469 were typically randomly spaced. However if the readout commands came at a 470 fixed frequency, a resonant Lorentz force could cause the wire to break from 471 mechanical fatigue. It had been shown that some resonant frequencies of the 472 jumpers were in the 10 kHz range (which exactly matched the CDF L1A trigger 473 rate under certain conditions) and only a few kicks were necessary to excite the 474 jumpers [10]. These resonant readout conditions would arise when there were 475 synchronous L1As from calibration triggers, faults in the trigger hardware, and 476 ladders with large and fixed length readout. The silicon detector was removed 477 from all calibration triggers and faulty trigger hardware was replaced. L00 had 478 large fixed readout, discussed in section 3.7, and its separation from the SVX-II 479 readout (Section 3.7.1) was necessary to mitigate the resonances. 480

481 3.6.1. Operational Mitigation

During the initial investigation, it was understood that the damage was 482 correlated with the L1 trigger rate. The maximum L1 trigger rate was set to only 483 12 kHz, where the typical peak rate was about 20 kHz. A limit was implemented 484 in the DAQ software, called the trigger handbrake, that would halt data taking 485 if the four-second-average of the L1 trigger rate exceeded the maximum rate. 486 After the wirebond resonance was discovered and the Ghostbuster protection 487 system was commissioned, the maximum rate was raised to 35 kHz. In addition, 488 an administrative procedure required that every change to the trigger system 489 was tested without the silicon detector and signed-off by the silicon operation 490 group. 491

⁴⁹² 3.6.2. Ghostbuster protection system

Given that it only took a few kicks at a $\sim 10 \, \text{kHz}$ resonance frequency to 493 excite a resonance, the *Ghostbuster* [30], already developed for SVT, was re-494 programmed to detect the onset of a resonance condition within ~ 1 ms. The 495 Ghostbuster paused data taking as soon as a series of synchronous readout com-496 mands had been detected. The FFO was modified to send readout commands to 497 the Ghostbuster. The addition of the Ghostbuster was essential to allow CDF 498 and the silicon detector to acquire data at the highest L1 rates. Without the 499 development of this board, the CDF physics program would have been severely 500 limited. After the introduction of the hardware protection system, losses of the 501 r-z side in ladders due to resonant conditions were eliminated, except for two 502 cases in 2005 and 2007 (Fig. 7). After the commissioning of the Ghostbuster, 503 the trigger handbrake remained as a redundant limit on the L1A rate. 504

The Ghostbuster algorithm paused data taking when it appeared that the 505 timing of readout commands was within a narrow frequency band. The Ghost-506 buster recorded the time interval between successive readout commands. A 507 difference in successive intervals of less than 1 μ s was counted as a *tick*. If the 508 difference in successive interval lengths was greater than 1 μ s, the tick counter 509 was reset. A resonance error was declared when the tick counter reached a preset 510 threshold, typically set to 11. The threshold value was initially determined from 511 a Monte Carlo simulation of the DAQ, and tuned to running conditions when 512 necessary. There was always a non-negligible chance that a set of consecutive 513 random L1 triggers would look like a resonance, and the threshold set point was 514 a compromise between detector safety and limiting false resonance alarms. 515

Figure 6 shows the the number of resonances per week detected by the Ghostbuster during all of Tevatron Run II. The spikes in the number of resonances per week were mostly caused by faulty trigger hardware or long readout times for ladders. The typical rate, neglecting those originating from faulty trigger hardware, was about 10 resonance errors per week (1.4 per day) consistent with stochastic operation.

As mentioned previously, any ladders with long fixed readout would exacerbate the likelihood of resonances at some L1 rates. The readout time could increase from corruption of the pedestal subtraction algorithm or if the noise level had grown. In both cases, the ladder readout time is no longer dictated by



Figure 6: A historical account of the number of resonance per week detected by the Ghostbuster. The maximum number of ticks, which triggered the Ghostbuster resonance detection, varied from 10 to 13 ticks during Run II, and eventually settled at 11. The spikes in the resonance rate are mostly due to faulty trigger hardware. The typical resonance rate was 10 per week (1.4 per day).

detector occupancy but rather ladder noise. This could lead to approximately 526 fixed long readout times. Also some chips in a chip chain were switched to 527 read-all mode to fix some errors, which also increased the readout time. During 528 2009-2010, the noise level in a handful of ladders had grown large enough, and 529 consistent enough in length, that the number of resonances increased and grad-530 ually forced the peak L1 trigger rate to be limited to 25 kHz. The problematic 531 noise growth was due to malfunctions in the chip or the sensor itself, and was 532 several times larger than the noise growth due to radiation damage observed in 533 most ladders. The noise was often isolated to a few chips of the chain, and by 534 increasing the NN sparsification threshold of the affected chips, the noise was 535 suppressed without compromising the data from other chips in the ladder. With 536 this noise suppressed, the peak L1A rate was increased to 32 kHz counts during 537 normal data-taking, without creating resonances. 538

539 3.7. LOO Noise

L00 was included to improve the precision of measuring displaced vertices that was essential for the discovery for B_s oscillations [31]. Unlike SVX-II and ISL, the L00 readout chips were not mounted directly on the L00 sensors to minimize the amount of material and so reduce the effects of multiple scattering. Instead, a fine-pitched cable connected the sensors to the readout chips. After L00 installation, significant noise was observed on the L00 readout that manifested as large pedestals that varied across a chip and with each event, with the largest variation at the edges of the readout cables. These pedestals could not be removed by DPS. An investigation concluded the noise was picked up by the fine-pitched readout cables [8].

L00 was forced to operate in read-all mode and the pedestals were removed by an offline event-by-event correction. During the offline data processing, the recorded charge across a chip was fit to Chebyshev polynomials to extract the pedestal. Tests using simulation were performed to check for biases from fitting and none were found [8].

555 3.7.1. Two-SRC Mode

The original silicon DAQ read out SVX-II, ISL and L00 together. A consequence of operating L00 in read-all mode was that it had the largest data volume and was fixed length, which exacerbated the wirebond resonances (Section 3.6). As L00 and ISL were not used by SVT, they were separated from SVX-II DAQ and read out by a separate SRC after a L2 accept. This improved the readout time and also mitigated the wirebond resonances.

562 3.7.2. Load Balancing

During Tevatron Run II, the peak instantaneous luminosity increased from 563 $50 \times 10^{30} \,\mathrm{cm}^{-2} \mathrm{s}^{-1}$ to $400 \times 10^{30} \,\mathrm{cm}^{-2} \mathrm{s}^{-1}$ and this had two consequences: higher 564 detector occupancy and an increased trigger rate. Without improvements to 565 CDF's trigger and DAQ, CDF would not have been able to operate at this 566 high instantaneously luminosity. In particular, some data segments arriving at 567 the event builder were significantly larger than others, and the event builder 568 performance was limited by the largest of these data segments. To mitigate this 569 effect, the number of VRB crates was expanded for both silicon and non-silicon 570 systems, and data rates were equalized across the crates. 571

As described in Section 3.4, data from the CDF silicon detector was buffered on VRBs until a L2 decision arrived. Each VRB crate was read out in parallel and the total readout time was dictated by the L00 VRB crate as it had the largest data volume. The L00 VRB crate had a fixed event size of 28 kB per event as a consequence of its read all mode (Section 3.7).

The readout time was reduced by mixing ISL and L00 VRBs to balance the data volume across VRB crates, thus reducing the peak data volume per VRB crate. A configuration was found and implemented during the 2006 Tevatron shutdown. The maximum event size of a single crate reduced from 28 kB to 20 kB.

Despite the success of the load balancing, the increased instantaneous luminosity of the Tevatron forced another re-optimization of the CDF DAQ. For the silicon DAQ, balancing the load across VRB crates was no longer sufficient. An additional VRB crate was added to the L00/ISL readout and remained in operation until the end of Run II.

587 3.8. Operational Experiences and Improvements

The commissioning of the CDF silicon detector was completed at the start of 588 2003 and the detector was included safely in normal data taking. This section de-589 scribes the routine day-to-day problems that persisted to the end of Run II. The 590 issues that affected the silicon DAQ on a daily basis were broadly categorized 591 as effects from single-event-upset and bit errors. Procedures were developed to 592 resolve common problems but required constant vigilance by the detector op-593 erations shift crew. Another issue, which persisted, was the full-detector trips, 594 where either subdetectors, or the complete silicon detector would switch off. Al-595 though far rarer, typically four times per year, it took 45-60 minutes to recover 596 and resume data taking. Another large component of detector operation was 597 the daily maintenance of the 580 ladders and 5644 readout chips. With such a 598 large number of components, at least one readout chip and/or ladder required 599 some daily adjustment. 600

601 3.8.1. Impact of ionizing radiation

A sizable fraction of the DAQ system was installed in the CDF collision hall, which was subjected to radiation from the Tevatron's colliding beams. As a result, the majority of electronics failure were due to radiation induced single event upsets (SEU). A SEU is a change of state caused by radiation striking a sensitive component in an electronic device. The change of state is a result of the free charge created by ionization in or close to an important logic element or memory bit.

During Run II, the Tevatron substantially reduced radiation rates, thereby reducing the radiation induced failures. At the end of Run II, the rates were so low that they fell below the detectable threshold of the radiation monitoring counters during the course of a Tevatron store. Also, the introduction of the Silicon-Autorecovery (SAR) in 2008 automated the detection and recovery of these SEU failures of the DAQ and the power supplies. It reduced interruptions to data taking from 10-20 minutes to less than five minutes.

Reinitialization of Chip Chains. During data taking, the current consumed by 616 the analog FE of a SVX3D chip chain (Section 3.3.1) could spontaneously drop 617 by 80-100 mA, implying one chip in the chain was not recording any data. This 618 typically occurred at rate of once or twice a day. A program dedicated to 619 monitoring the power supplies sent an alarm to the DAQ if such a drop in chip 620 current was detected, and the data taking was paused for less than a minute 621 to reinitialize the chip chain. Overall, this only had a minor impact on data 622 taking. 623

FIB Bit Errors and FIB FPGA Burnout. Each FIB had 16 FPGAs, and thus a higher rate per board of SEU damage than the other VME modules. Data corruption errors were resolved by reloading the FPGA programs of the affected FIB, which typically occurred 1-2 times a day. On rare occasions (3-4 per year), one of the FPGAs would enter a high current state and blow a fuse on the board. In a majority of cases the affected FPGA had to be replaced, and in the remaining cases, a reprogramming of its firmware was needed.

⁶³¹ 3.8.2. Bit Errors in the Data stream

As the silicon DAQ is data driven, the data format had to be self-describing 632 to identify not only the amount of charge but also the location where it was 633 recorded. Therefore any corruption of the data implied more than just errors in 634 digitization. During operations, several sources of bit errors in the data stream 635 were detected and immediately addressed. While some errors, especially those 636 from on-detector components, could not be repaired, many could be corrected in 637 the offline reconstruction. Operating the SVX3D readout in nearest-neighbor 638 mode guaranteed at least 3 consecutive strips would be read, and the error-639 correction algorithm could exploit this feature to identify and correct single-bit 640 errors. 641

Bit errors in the optical links. One common instance of bit errors in the data
stream was in the DOIM system. At the start of Tevatron Run II, most DOIM
bit errors were traced to bad electrical contacts in the sockets that held the
RX in the FTM. Gold plating the pins of those devices to establish a better
connection with the sockets eliminated this source of bit errors.

During Tevatron Run II, the typical DOIM bit errors manifested as bits 647 that were stuck low or high in the data stream, which corresponded to either 648 a malfunctioning RX unit or TX unit. Faulty RX units were accessible and 649 replaced from a pool of spares when necessary. Faulty TX units were inaccessible 650 and thus irreplaceable. Some TX failures could be recovered by adjusting power 651 supply settings to tune the TX unit light output. Another class of TX-related 652 errors were linked to bad connections in a circuit board which served as the 653 interface between the sensors and the power supplies. These boards were located 654 just outside the tracking volume and were accessible only when the Tevatron 655 was shut down for at least a week. In these instances a borescope and a custom 656 tool were used to push the circuit board back into place to re-establish the 657 electrical connection. 658

Bit errors in the Readout boards. The FIB occasionally caused bit errors in the
data stream, most commonly due to SEUs and component failures. SEU related
bit errors were resolved by reloading the programs to the FPGAs on the boards.
FIBs boards with failed components were replaced. On rare occasions (less than
once per year), VRB boards gave bit errors that were traced to component or
printed circuit boards failures and were replaced.

665 3.8.3. Full Detector trips

There were several incidents in which most or all SVX3D chips in the silicon detector would go into a high current state leading to power supply trips. These trips occurred in some or all of the SVX-II, ISL, and L00 sub-detectors and occurred more frequently in the winter season. On average, it took about 45-60 minutes to recover from these incidents.

Only some of the sources of these trips were reproducible and the remainder were hard to diagnose and resolve due to their rarity. While the origin of all these trips was unknown, many potential causes were identified and eliminated

as sources of the problem. It was observed several times that personnel working 674 near the electronics area could induce this problem, suggesting that loose or 675 corroded contacts may have been a source; the re-seating and replacing of many 676 key components proved inconclusive. It was also suspected that differences in 677 grounding levels between the racks could generate this problem, but no evidence 678 of a bad ground was found. Another of these sources was the corruption of the 679 clock signal and consequent lack of keep-alive commands sent to the chip, as 680 detailed in Section 3.5.1. The underlying reasons for corrupted clock inputs 681 were not clear, and many full detector trips did not show any indication of 682 clock corruption. 683

It was found that some of these trips did occur in coincidence with a high-684 voltage power supply trip of one particular muon detector chamber. The muon 685 detector chamber was powered with 3500 V and had a current draw of about 1 686 mA. The trip of its power supply during these incidents was attributed to arcing 687 between the high-voltage lead and the chamber ground. The hypothesis that 688 an arc in a completely unrelated subsystem would give rise to a massive power 689 trip in the silicon detector was tested by inducing an arc in the muon detector 690 chamber and observing the behavior of the silicon detector. The arc was forced 691 by closing in the high-voltage lead to the ground until a spark was generated, 692 and full subdetector trips in the silicon detector were reliably reproduced each 693 time the spark was induced. The mechanism was believed to be electromagnetic 694 pickup between the muon chamber high voltage distribution cables and the clock 695 crate during the occurrence of the spark. The electromagnetic field bursts were 696 observed by carefully-placed coils in the surroundings of the clock crate. The 697 pickup induced a change in the ground level of the clock signal, which exceeded 698 the specification for the silicon electronics, resulting in an effective lack of clock 699 signal during a period of time of about a few microseconds; thus no keep-alives 700 were sent during this clock interruption. This problem was solved by reducing 701 the voltage applied to the defective muon detector chamber to 3200 V. 702

703 3.9. Summary of DAQ Performance

The CDF silicon DAQ was incredibly complex in order to meet the chal-704 lenges of providing data to SVT. Its performance during Tevatron Run II was 705 defined by three major phases: commissioning (2001-2003), steady operations 706 (2004-2008), end of Run II (2009-2011). The long commissioning period was 707 directly due to the large number of unexpected problems that were apparent 708 only after installation of the silicon detector. The challenge of tackling these 709 problems simultaneously (in addition to a number of non-DAQ issues), while 710 attempting to take data simultaneously was considerable. However after this 711 commissioning period, the silicon DAQ entered a stable period and efforts to 712 optimize the performance and operations were carried out, in addition to daily 713 maintenance of the DAQ components. From 2009, the dwindling pool of working 714 spare components and the effects of radiation were taking their toll. 715

Figures 7 and 8 are historical records of the different types of errors accrued types the DAQ electronics during Tevatron Run II, expressed as the fraction of ⁷¹⁸ bad readout chips. Figure 7 shows the SVX-II $r-\phi$ and r-z sides separately. The ⁷¹⁹ definition of the different errors are:

- AVDD2: SVX3D errors diagnosed as AVDD2 type errors (Section 3.5.1)
- SVX3D: SVX3D errors that are not AVDD2 type error (Section 3.5.1)
- Detector: Faults which originate in the silicon sensor
- *Optical*: Errors which are from DOIM TX or RX
- Jumper: Ladders whose r-z side was lost from wirebond resonances (Section 3.6)
- Cooling: Ladders turned off due to lack of ISL cooling (Section 5.2.1)
- *Hardware*: Error and faults which do not match any of the categories defined above

During the commissioning phase, the number of bad chips (ladder) grew as 729 the different problem manifested, then stabilized in 2003 (steady state running). 730 The r-z plots in Fig. 7 shows that there were only 4 additional jumper failures 731 after the inclusion of the Ghostbuster and none of these was an immediate 732 consequence of beam incidents or resonant conditions. After the inclusion of the 733 Ghostbuster, data was taken safely and reliably with peak L1 trigger rates in 734 excess of 25 kHz - essential for CDF physics. The failure rate of chips after 2003 735 is far lower compared to the commissioning period. Most of the different failure 736 categories stabilized. From 2009, the chronic effects of radiation damage and 737 aging were starting to take their toll on the silicon detector. The failures from 738 SVX3D and optical were steadily increasing and half the total radiation dose 739 was delivered between 2009-2011. With the increased radiation, components 740 started failing more often, shrinking the pool of spare components. These plots 741 742 also highlight other problems of the silicon detector that affected the DAQ. Figure 8 shows a large rise and fall in the fraction of bad ISL chips during 743 2003 due to blocked cooling line and its eventual clearance; this is discussed in 744 further detail in section 5. 745

At the end of Run II, 84% (73%) of all SVX-II $r-\phi$ (r-z) and 89% of all ISL SVX3D chips continued to function without error and did not compromise the silicon detector tracking performance. This is an impressive feat as the CDF silicon was designed to be replaced after the first 2-3 fb⁻¹, about three years. It survived four times the radiation dose and lasted three times longer than the original design.

752 4. Power Supplies

The CDF silicon detector used power supply modules manufactured by CAEN. A total of 114 custom modules were housed in 16 SY527 mainframe crates located in the corners of the CDF collision hall. The crates were elevated



Figure 7: A historical account of the different errors and faults accrued by the SVX-II r- ϕ (top) and r-z (bottom) SVX3D chips during Tevatron Run II. Each error category is defined in Section 3.9. At the end of Tevatron Run II, 84% r- ϕ and 73% r-z SVX chips were still operating without error.

⁷⁵⁶ 2-7 meters off the floor due to space constraints in the collision hall. This lo-⁷⁵⁷ cation had a distinct disadvantage; the supplies and crates were continuously ⁷⁵⁸ exposed to radiation, which not only shortened the life of many internal elec-⁷⁵⁹ tronic components, but also resulted in single event upsets that required a crate ⁷⁶⁰ reset and in single event burnouts that necessitated additional hardware pro-⁷⁶¹ tection for the detector. Investigation or replacement of a problematic power ⁷⁶² supply required access to a radiation controlled area for 1-2 hours.

763 4.1. System Overview

One power supply module provided low voltages (2 V and 5 V) to the portcard, low voltages (5-8 V) to the SVX3D chip chains, and high voltage (up to



Figure 8: A historical account of the different errors and faults accrued by the ISL SVX3D chips during Tevatron Run II. Each error category is defined in Section 3.9. At the end of Tevatron Run II, 89% of ISL SVX3D chips were still operating without error.

766 500 V to bias the sensors of one wedge of the silicon detector. The low voltages were set via potentiometers on the side of the supply, while the high voltage was 767 set via software on the SY527 crate. All channels had a maximum voltage set-768 ting. If the channel voltage exceeded its maximum, an "overvoltage" error was 769 met and the power supply cut power to the affected channel. These limits were 770 also set via potentiometers on the modules. Any adjustments to the low voltage 771 or the maximum voltage settings had to be done with the supply inserted into 772 the crate and the crate powered. Because of this need and the location of the 773 potentiometers, changing these settings were not possible in the collision hall, 774 rather it had to be done on a test stand, using a specially modified crate. 775

The SY527 crate had an RS-232 interface for connection to a computer, as 776 well as a Lemo input to reset the crate remotely. In addition, the crate had a 777 proprietary serial communications port, which connected to a V288 high speed 778 CAENet VME Controller. The V288 connected to another controller card in the 779 same crate which had an ethernet port for external communications. A VME 780 crate was used to communicate with all the crates in the collision hall this way, 781 and a Java program provided a graphical interface of the power supply controls. 782 A PC monitored and logged parameters, including power supply voltages, cur-783 rents, and the time of last communication for each power supply crate. This 784 PC logged parameters for the cooling system as well (see Section 5). 785

786 4.2. Decreasing Low Voltages

In 2005, after over 4 years of data taking, low voltage channels of several
power supplies were found to drift erratically from their nominal values. Specifically, filter capacitors in a particular regulator circuit of each low voltage channel
gradually lost their capacitance, causing the low voltage supplied by the circuit

⁷⁹¹ to drop over time, typically a tenth of a volt over the course of three months.

The solution must be sub-solution files files are site (22 in total).

The solution was to replace all of the filter capacitors (32 in total) on the supply. This repair was done on-site at FNAL, and typically only took a few hours. The swaps were usually not urgent (the readout electronics would still work at 0.5 V below nominal), and were done when another problem in the detector required an access to the collision hall. Figure 9 shows the analog low



Figure 9: An analog low voltage line powering a series of SVX3D chips of an SVX-II ladder is seen dropping gradually over time. The vertical dashed line marks the replacement of the faulty power supply.

797

voltage channel of an SVX-II ladder drifting over a period of two years. The
vertical dashed line marks the time when the faulty power supply was replaced,
restoring the low voltage to its nominal value. The gaps in the plot correspond
to Tevatron maintenance shutdowns. During the 2007 (2009) shutdown 47 (21)
supplies out of a total of 112 were repaired and replaced. Most of the remainder
were replaced gradually a few at a time utilising the spare pool in hand.

⁸⁰⁴ 4.3. Single Event Upsets

A consequence of the power supplies being located in the radiation environment of the collision hall was that both the crates and supply boards were subject to single event upsets. This typically only required the crate to be reset. Even so, every reset costed a few minutes of data acquisition time.

The SY527 crates had a Lemo input for remotely resetting the crate; the 809 reset cable ran from the crate to the counting room outside the collision hall. 810 Thus, the shift crew could reset the crate when necessary, although the pro-811 cedure, from indentification of a problem to manually turning the supply on 812 again, took about 10 minutes. In order to eliminate any delay due to human 813 intervention, an automatic system was developed to detect when a particular 814 crate has stopped communicating its voltage and current readings. Once this 815 state was detected, the automatic reset system sent the reset signal to the crate. 816 The supplies had to be turned on again once the crate had rebooted. Recovery 817 from an automatic crate reset was automated with the development of Silicon 818

Auto-Recovery, described in Section 8.1, which reduced the downtime from such incidents from ten minutes to less than five minutes.

The supplies themselves were also subject to radiation induced effects. Specifically, certain power metal oxide semiconductor field effect transistor (MOS-FET) components of the L00 supplies underwent single event burnouts (SEBs) [32], causing the supply to output its maximum bias voltage. If this were to happen with the detector connected, it could result in permanent damage to the silicon sensors. Fortunately these SEBs were first observed during commissioning, before the detector was connected.

In order to prevent potential damage, compact voltage fuses, called *crowbars*, were developed and installed. The crowbars interrupted the current if the bias voltage exceeded a specified voltage. They were placed between the high voltage detector cable and the supply itself. The initial crowbars protected the sensors from bias voltages above 150 V. In 2008, when radiation damage necessitated operating at larger bias voltages, new crowbars with a voltage limit of 450 V were installed.

835 4.4. Operational Experience

Ten years of experience in operating the power supplies helped the detector operation crew identify potential problems and react to them before they caused significant downtime. Many improvements were made, mostly to the procedures used to test supplies after repair or work in the collision hall.

840 4.4.1. Testing Procedures

All the repaired supplies were run through a series of tests, designed to mimic the operating conditions in the collision hall, before their installation in the detector. These included long periods of being powered on (burn-in), as well as rapid power cycling. The former were crucial to detecting intermittent problems.

The testing procedure consisted of connecting the supply to a set of static impedance loads (a loadbox), and turning the supply on for approximately 24 hours. It was followed by a test that turned the module on and off every 2 minutes for approximately 24 hours. The currents and voltages read out in each cycle were analyzed to ensure stability.

If a module was forcibly switched off for its protection ("tripped") during the first 24 hours or any currents or voltages were unstable during the second, the module was sent for additional inspection or repair. The safety features of the module were also tested to verify it tripped properly under limiting conditions of voltage and current and when the supply enable signal was absent.

In addition, the power supplies were tested in the collision hall just before their deployment in the detector. The procedure to check out a supply in the collision hall consisted of connecting it to a loadbox and turning it on. Currents and voltages as read back from the module were recorded, and voltages were measured and compared at the loadbox. The safety features were tested again to make sure that the supply tripped off at intended voltage and current conditions. Then, the supply was connected to the sensors, and turned on. Given the location of the crates, the RS-232 interface provided the optimal method of testing, as it allowed easy control of the module using a laptop on the collision hall floor.

The loadbox was made by the Computing Division ESE at FNAL and incorporated different load resistances for L00 and SVX-II/ISL supplies with capability to switch between them. It utilized an ADC to automatically measure the voltages on each channel. With the loadbox, the collision hall check-out procedure was quick, reliable and reproducible.

871 4.4.2. Damage to Power Supplies During Transportation

When power supply modules could not be repaired on site, they were sent back to the manufacturer in Italy. Shipping the modules back to Fermilab damaged more than half of the shipped power supplies. In 2008, a short study was done to examine the shipping method adopted by the manufacturer and implement improvements to prevent future breakage.

In order to streamline the transit and prevent breakage, a set of procedures 877 was devised for the manufacturer to follow when shipping supplies back. First, 878 instead of routing via CAEN's business office in New York, the modules were 879 required to be shipped on a direct flight from Italy to Chicago. Second, the 880 supplies were to be shipped on a standard shipping pallet, requiring the use of 881 a forklift to prevent the box from being mishandled. Finally, an accelerometer 882 inside the box and shock/tilt sensors affixed to the outside of the box were used 883 to monitor the detailed motion the supplies were subjected to while in transit. 884 Using these procedures, every supply that was shipped back to Fermilab arrived 885 in working order. 886

⁸⁸⁷ 5. Cooling System

5.1. System Overview

The sensors had to be kept chilled at all times in order to prevent migration of radiation-induced defects, which shorten the working lifetime of the detector, and to reduce the sensor leakage current, which increases with radiation damage. The SVX-II, ISL, and L00 detectors were cooled by two closed-circuit liquid cooling systems. One system, shown in Fig. 10, was used to cool SVX-II and L00. A second separate system was used for ISL, although some of the cooling control electronics and interlocks were shared.

⁸⁹⁶ Due to the higher radiation levels close to the beam line, the operating tem-⁸⁹⁷ perature of L00 and SVX-II was chosen to be lower than ISL. The temperature ⁸⁹⁸ of the coolant out of the chiller was -10 °C for SVX-II/L00 and +6 °C for ISL. ⁸⁹⁹ The coolant for SVX-II/L00 was a mixture of 30% ethylene glycol and 70% wa-⁹⁰⁰ ter by weight, and the coolant for ISL was distilled water. Both coolants warmed ⁹⁰¹ up by a degree or two in the piping between the chillers and the detector. The ⁹⁰² total cooling load for SVX-II/L00 during operation was approximately 5 kW,



Figure 10: Schematic of the SVX-II/L00 cooling subsystem. The subsystem for ISL can be described in the same manner, though both subsystems share the same PC and control/interlocks crates.

and that of ISL is approximately 4 kW. About half of this heat load was pro-903 duced by the silicon detector and the remainder was heat transferred from the 904 warmer surroundings. Most of the heat generated by the silicon detector was 905 produced by the SVX3D readout chips. All of the portcards were cooled by the 906 ISL system because the temperature of the ISL system was within the range of 907 the optimal performance of the light transmitters. In order to prevent water 908 from condensing on the sensors and electronics, dry nitrogen flowed through the 909 silicon detector volume. 910

In the SVX-II ladders, the electrical hybrids were cooled through thermal 911 contact to beryllium support bulkheads, with integrated cooling channels. For 912 L00 and ISL ladders, and for the portcards, cooling was achieved through ther-913 mal contact to aluminum tubes glued to the mechanical supports. The SVX-II 914 and ISL sensors were not in close thermal contact with the coolant, however, 915 nor were their temperatures directly monitored. Based on the measurements 916 of the ambient temperatures and the bulkhead temperatures and on thermal 917 models, we estimated the temperatures of the sensors while the detector was 918 powered to be between 0 and $10 \,^{\circ}\text{C}$ for SVX-II, and between 15 and $25 \,^{\circ}\text{C}$ for 919 ISL. The L00 sensors, however, were in close thermal contact with the coolant 920 tubes, and their temperature was about -5 °C when powered. 921

In order to prevent damage to the electronics if a coolant pipe leaked, all 922 cooling pipes were operated below atmospheric pressure so that a leak in a 923 pipe or a fitting would draw nitrogen into the cooling system rather than leak 924 coolant into the detector volume. The cooling system had vacuum pumps and 925 air separators in order to maintain the sub-atmospheric pressure in the system at 926 all times. Two vacuum pumps were available per system, with one running and 927 one piped in as an immediately available spare, switchable with electronically 928 controlled valves. 929

The coolant was circulated by pumps on the two chillers: one for SVX-II/L00, and one for ISL. A third chiller was available to be used as a spare in case of failure of either chiller. This system was used successfully in November 2004, when the spare chiller was used for two days while a leak in the ISL chiller was identified and fixed.

Each of the SVX-II/L00 and ISL chiller circuits had a set of filters — a microparticle filter, a UV sterilizer to limit biological activity in the coolant, and a resin-cartridge de-ionizer. The conductivity of the coolant was regulated to be approximately 0.6 μ S/cm. The pH of each of the two coolants was monitored via weekly samples drawn from the air separators and both stayed near a pH of 6.

To ensure the safety of the silicon detector, a series of interlocks prevented 941 the power supplies from being turned on when insufficient cooling was avail-942 able, and coolant flows were switched off if an unsafe situation existed. If the 943 pressure in any of the cooling lines rose to within 1 psi of atmospheric pressure, 944 electrically controlled solenoid values on the coolant supply lines to the affected 945 detector subsystem were shut automatically. If dewpoint sensors detected that 946 the dewpoint was within 3° C of the minimum temperature in the detector 947 volume, then flows were shut off. 948

The interlock system had the ability to disable power to the detector. The 949 CAEN power supply modules required a voltage of +5 V in a Lemo connector 950 in order to enable detector power. Dropping of this +5 V had the effect of 951 switching the power off. If there was insufficient flow of coolant to the detector 952 or if temperature sensors indicated that a coolant temperature was too high 953 then the detector power supplies are turned off via the +5 V control lines. The 954 electronics crates that housed the CAEN modules monitored the temperature 955 of the electronics and the status of the crate fan pack, and would shut off if a 956 failure was detected. 957

These interlocks were controlled by a Siemens SIMATIC 575 Programmable Logic Controller (PLC) [33], attached to two crates containing modules that read out temperature, pressure, and flow transducers. A third crate provided control for the solenoid valves, the vacuum pumps, the chillers, and the 5 V power supply enable lines.

A second layer of interlocks was provided by a Siemens QUADLOG CCM+ 963 PLC [34]. This controller had an independent readout of the coolant flows 964 and pressures and also monitored the state of the power supply interlocks. If 965 power supplies were permitted to be turned on but coolant flows were too low 966 (< 1 LPM) — which could only happen if the first PLC's interlocks had failed this interlock system would turn off the power to the silicon power supply 968 and FIB racks (section 3). The QUADLOG system also protected against over-969 pressure conditions — again in the event of a failure of the first PLC system – 970 by shutting down coolant flows. 971

During a power outage, backup systems kept the cooling system functioning 972 at a reduced level. Power was supplied to the PLCs and control electronics 973 from an uninterruptible power supply (UPS), which was backed up with a diesel 974 generator. The vacuum pumps were powered by the diesel generator but not the 975 UPS, and therefore they did not pump during the time required for the diesel 976 generator to start up at the beginning of a power outage, but resumed pumping 977 shortly into the outage. CDF's building water chillers did not operate during a 978 power outage, and so a dedicated air-cooled backup chiller, which was powered 979 by the diesel generator, was able to supply chilled water to the SVX-II/L00 980 chillers. The ISL chiller's compressor did not operate during a power outage, 981 but a backup coolant pump maintained coolant circulation. 982

983 5.2. Operational Experience

The cooling and interlock system for the CDF silicon detector had a high 984 reliability and failed infrequently. The main goals of protecting the silicon detec-985 tor and preventing any damage to other detectors were well fulfilled. However, 986 a few major incidents affecting the ISL cooling structure inside the detector 987 revealed the inadequacy of the interconnected branching scheme of the cooling 988 piping (see Fig. 11). Isolation of leaky segments (Section 5.2.3) was very dif-989 ficult and required a multi-week shutdown of the detector. During these down 990 times a great deal of work was invested to investigate and repair leaks. In con-991 trast, the SVX-II/L00 cooling system, which had a simpler geometry, was more 992 stable and performed better. 993



Figure 11: Diagram of the connections of the cooling lines of the east half of ISL showing the supply and return manifolds located in the detector frame. Flow which enters the detector via one of the four supply lines was be shared among several return lines. Electronic supply valves and manual return valves are shown.

994 5.2.1. Blockage of Cooling Flows in ISL

When the ISL detector was commissioned, it was discovered that 35% of 995 the lines in ISL were not cooling. Further investigation using long borescopes 996 showed that the coolant flow was blocked by epoxy found at aluminum right-997 angle elbows in these cooling tubes. In 2002 and 2003, these blockages were 998 opened by shining Nd:YAG laser light to vaporize the epoxy. A pulsed laser 999 operated at an average power of 10–40 W was used, guided by an optical fiber 1000 with a 400 μ m core and a 20 μ m Al jacket. The fiber was attached at the end to 1001 a device holding a prism at a right angle so that the laser light could be aimed 1002 at the epoxy plugs just beyond the bends of the elbows. 1003

This operation was delicate and difficult, as the coolant piping had an inside 1004 diameter of 4 mm and the elbows were approximately two meters away from 1005 the accessible end of the tubing. One cooling line was found to be extremely 1006 difficult to open and during the attempts the prism holder became detached 1007 from the fiber and remained lodged inside the pipe. The flow in the line was 1008 not restored, and a concern of leaks developing due to stagnant coolant with 1009 corrosive ions building up made it prudent to plug the narrow tube. Aluminum 1010 plugs were inserted at the manifolds where the cooling supply and return lines 1011 divide into four or five narrower tubes. A second prism holder was stuck in 1012 another narrow tube and repeated attempts to remove it failed. This reduced 1013 the flow, but did not block it. 1014

¹⁰¹⁵ The successful opening of the blocked ISL flows raised the fraction of working ¹⁰¹⁶ ISL cooling lines from 65% to 96%.

1017 5.2.2. Degradation of Coolant and Corrosion

In 2005, the SVX-II chiller setpoint was lowered from -6 °C to -10 °C in 1018 order to extend the longevity of the silicon detector. After this change to the 1019 operating temperatures, there was an incident during routine maintenance work 1020 on the ISL vacuum pump that accidently fired the safety interlocks of the cooling 1021 system. This stopped the flow of ISL coolant for at least 30 minutes. The ISL 1022 cooling system also serves as the cooling for the portcards for the entire silicon 1023 detector and during this period, the coolant in the SVX-II portcard cooling 1024 lines began to freeze due to their proximity to the SVX-II cooling system which 1025 was at -10 °C. This constricted the flow of coolant in the SVX-II portcard lines 1026 to less than the accepted minimum rate for the safety interlocks which in turn 1027 did not permit the SVX-II detector to be powered. The frozen coolant in the 1028 SVX-II portcard line was melted by raising the SVX-II coolant temperature from 1029 -10 °C to +6 °C and turning the ISL on to raise the ambient temperature. After 1030 two hours, flow was reestablished to the SVX-II portcard lines which allowed 1031 the SVX-II detector to be powered. In order to prevent freezing incidents, which 1032 risk portcard line ruptures, 10% of ethylene glycol by weight was added to the 1033 ISL coolant. 1034

In 2007 the pressure in an ISL portcard supply line rose beyond the op-1035 erational tolerance due to leaks in the aluminum manifold which distributes 1036 the coolant to the portcards. Sufficient flow could not be maintained to cool 1037 the silicon sensor readout electronics and the east half of the detector had to 1038 be switched off. The investigation found that the pH of the ISL coolant had 1039 dropped to approximately 2.0. The conductivity had risen from 2 μ S/cm to 1040 around 3000 μ S/cm. Unfortunately, the conductivity meters at that time satu-1041 rated at values far below 3000 μ S/cm. An analysis based on ion chromatography 1042 revealed that the ethylene glycol had degraded into light organic acids, mainly 1043 formic acid at a concentration of 12.5 g/l (0.265 moles/l). Another analysis 1044 ruled out the possibility of microbial-induced degradation. There was evidence 1045 that warming up the ISL detector to 13 °C during a two month shutdown in 1046 the summer of 2006 accelerated the acidification in correlation with the rise in 1047 conductivity. Several system components corroded faster than others with this 1048 degraded coolant. Outside the detector, the brass valve stems of the solenoid 1049 flow control valves had corroded, causing failures in the valves weeks before the 1050 operational collapse. The portcard manifolds were made with aluminum 5052 1051 piping welded using aluminum 5356 filler [35]. The filler material had corroded 1052 more quickly than the piping material. 1053

The system was successfully repaired during a shutdown in the summer of 1054 2007. The repair work involved inspection of the system with a borescope. The 1055 affected manifolds were located at a distance of 1 m inside the cooling tubes. 1056 With the use of a custom-made tool, Scotch DP190 epoxy [36] was laid down 1057 on the welded area of the leaking manifolds. In order to prevent corrosion 1058 the coolant was replaced by deionized water, and the pH and conductivity were 1059 monitored frequently in order to identify and mitigate hazards quickly. Through 1060 the remainder of Run II, the pH and conductivity were stable, and the affected 1061

¹⁰⁶² portions of ISL were cooled.

The +6 °C cooling water supplied to the portcards and the heat generated by the portcards when powered were sufficient to keep the water from freezing during normal detector operation. When the portcards were not powered, however, a freezing hazard existed. Protection against freezing (the original impetus for adding glycol to the ISL coolant) was implemented via an interlock that inhibited flow to the SVX-II when the temperature measured in any portcard coolant circuit fell below 1 °C.

1070 5.2.3. Leaks in ISL

The overall leak-rate of the ISL coolant system increased steadily after in-1071 stallation. The leak rate, as determined by the amount of time it took to leak 1072 up to atmospheric pressure when the vacuum pumps were valved off, increased 1073 by a factor of five between 2007 and 2009, prompting a third intervention to 1074 extend the longevity of the ISL cooling system. The aluminum ladder-cooling 1075 tubing was found to be leak-tight, except for a few smaller leaks in two tubes. 1076 The epoxied joints between polyethylene tubing and the aluminum manifolds 1077 where the small aluminum cooling pipes join were found to be the leakiest in 1078 the system. Additional epoxy was applied to three of these joints, and the flow 1079 performance improved, but the overall nitrogen leak rate remained at compara-1080 ble levels as measured by the exhaust flow rate out of the vacuum pump. The 1081 flow rates and cooling performance were monitored closely for the remainder of 1082 CDF's data-taking run, and did not degrade to the point of requiring a change 1083 in the operation of ISL. 1084

1085 6. Particle Beam Incidents and Monitoring

The particles from standard Tevatron running conditions (physics runs with 1086 proton-antiproton collisions) were responsible for the vast majority of the ra-1087 1088 diation dose to the CDF silicon detector sensors and components. However, beam instabilities and sudden beam losses were an unavoidable part of running 1089 a large accelerator, and posed a threat to particle detectors. As described in 1090 Section 2, the silicon detector was the closest to the beam and suffered larger 1091 consequences than the other CDF sub-detectors. Beam incidents early in Run 1092 II resulted in large and acute radiation fields that permanently damaged about 1093 4% of the readout chips in the detector. A two-pronged approach was taken to 1094 reduce the possibility of additional damage from beam incidents: a thorough 1095 review of past incidents and a strict beam monitoring system. 1096

1097 6.1. Particle Beam Incidents

When a beam incident occurred, a thorough review of the problem, in collaboration with the Fermilab Accelerator Division, often resulted in stricter testing of any hardware involved in the incident, as well as procedural changes in accelerator operation. The following list briefly describes the main types of beam incidents and the measures taken to lessen their impact.

1103 6.1.1. High Beam Losses

Particles leaving the outer halo of the beams at CDF (beam losses) were 1104 measured by counting hits in scintillation counters located on both sides of 1105 the detector. The counters were gated to exclude hits coincident with proton-1106 antiproton collisions at the center of the detector. High losses at any time were 1107 indicative of higher radiation fields in the detector volume. More importantly, 1108 sudden changes in the losses indicated potential instabilities in the Tevatron 1109 beam. Monitoring software, described in section 6.2, would automatically ramp 1110 down the silicon sensor bias voltage after dangerous beam conditions were de-1111 tected. Under exceptional circumstances when the radiation increased dramati-1112 cally, fast hardware protection systems would issue an abort which immediately 1113 removed beam from the Tevatron (Section 6.2). 1114

¹¹¹⁵ 6.1.2. Kicker Magnet Pre-fires

A set of 10 *abort kicker magnets* were used to remove the circulating proton and antiproton beams from the Tevatron by steering them into a beam dump. The abort kickers have a finite rise time, so any beam which passed through those magnets as their field ramped up were not cleanly extracted into the beam dump. The beam train structure contained an unpopulated $1.4 \,\mu s$ gap, known as the *abort gap*, to allow the abort kickers to ramp up without affecting circulating beam.

Normally, beam aborts were synchronized with the abort gap so that the 1123 kickers would reach nominal field before the first bunches arrived to be sent to 1124 the dump. Occasionally, one of the 10 thyratrons that powered the individual 1125 abort kickers would trigger spontaneously. When such a *pre-fire* was detected, 1126 the other abort kickers were fired intentionally, without synchronizing to the 1127 abort gap, in order to abort the beam as quickly as possible. Any beam that 1128 passed through the pre-fired and other kicker magnets before they had reached 1129 nominal field could continue traveling with a distorted orbit, possibly hitting 1130 accelerator components and creating secondary and tertiary showers of particles 1131 at the experiments. The location of the abort kickers relative to the detector 1132 made CDF susceptible to large, acute doses from proton initiated showers. One 1133 such incident in 2003 resulted in the loss of about 4% of the silicon readout 1134 chips. After a thorough review of the incident, a new collimator was installed 1135 to intercept protons that would strike the CDF detector due to an abort kicker 1136 pre-fire. Although pre-fires continued to occur several times per year, after the 1137 installation of the new collimator, the silicon detector did not sustain significant 1138 damage from such incidents. 1139

1140 6.1.3. Quenches

A quench is the sudden transition of a superconductor from a state with zero electrical resistance to a normal state with small, but finite, electrical resistance. For superconducting magnets like those in the Tevatron, a quench could be caused by a temperature rise of the current-carrying superconducting cable above its critical temperature. This could be caused by localized beam losses in

the magnet or a loss of cryogenic cooling. An automated quench protection sys-1146 tem protected the magnets from potential damage caused by the sudden ohmic 1147 heating, generated by the large current powering the magnets when resistance 1148 became normal. The quench protection monitors (QPMs) monitored the resis-1149 tive voltage across a string of several magnets. When a quench was detected, 1150 the QPM simultaneously energized heaters within each magnet to enlarge the 1151 quenched region and enabled switches to bypass current out of the affected mag-1152 nets. In addition, it initiated a beam abort, to reduce the impact of the orbit 1153 distortion caused by the decaying magnetic field of the quenched magnets. 1154

A key component of protecting the silicon detector was the Tevatron QPM 1155 being able to detect a quench and abort the beam as early as possible. The 1156 early Tevatron QPM operated at 60 Hz, leading to quenches possibly remaining 1157 undetected for up to $16 \,\mathrm{ms}$ (>760 beam revolutions) between QPM measure-1158 ment cycles. Indeed, this shortcoming was at the heart of an incident in 2003 1159 that caused considerable damage to the Tevatron and to the experimental de-1160 tectors. When a movable experimental detector (Roman Pot) suddenly moved 1161 toward the beam, high beam losses scattered from the device caused a very 1162 fast quench of nearby superconducting magnets that likely went undetected for 1163 the entire gap between QPM measurement samples. The beams circulated for 1164 most of that time with highly distorted orbits that showered the experiments 1165 and accelerator components. A stainless steel collimator had a groove bored 1166 into its surface over half of its 1.5 m length. A review of the incident led to 1167 a higher bandwidth upgrade of the QPM system (to 5 kHz) completed in 2006 1168 which allowed quenches to be detected and beam aborted in $\sim 500 \,\mu s$ (25 beam 1169 revolutions). 1170

1171 6.1.4. Separator Sparks

In the Tevatron, the proton and antiproton beams circulated within a single 1172 beam pipe. Electrostatic separators kicked the beams onto distinct helical orbits 1173 so that head-on collisions occurred only at the CDF and D0 interaction points. 1174 These 26 separators were stainless steel, parallel-plate electrodes, 2.5 m long, 1175 with a 5 cm gap operating with a gradient of up to $\sim 40 \,\mathrm{kV/cm}$. Occasionally, 1176 a high-voltage breakdown (spark) occurred between the plates, or between a 1177 plate and the surrounding shell. The effects of a separator spark depended on 1178 which separator broke down, and when the spark occurred during a Tevatron 1179 cycle. Such breakdowns caused a momentary kick to the beams resulting in orbit 1180 distortions that caused beam loss spikes, emittance growth, and a small drop in 1181 instantaneous luminosity. The orbit distortion caused by a separator spark could 1182 be large enough to drive beam into collimators and cause quenches of nearby 1183 superconducting magnets. Improvements in the high voltage conditioning of the 1184 separators reduced the overall spark rate compared to early Run II conditions. 1185 During the latter years of Tevatron operations, only one or two stores per year 1186 terminated prematurely from a separator spark. 1187

1188 6.2. Beam Monitoring and Detector Protection

¹¹⁸⁹ CDF had a slow-reacting (of the order of seconds) software monitor and a ¹¹⁹⁰ fast-reacting (of the order of 10 μ s) hardware protection system to help prevent ¹¹⁹¹ damage to the silicon detector from the incidents mentioned in Section 6.1.

The software program, called TEVMON, collected several measurements that 1192 described beam conditions, some of which were provided to CDF by accelerator 1193 monitoring systems. These included beam losses, RF station voltages, instan-1194 taneous luminosity, abort-gap beam current, and abort kicker magnet voltages. 1195 A variable that entered the warning range caused an audible alert for the shift 1196 crew, which indicated degraded beam conditions that may warrant their atten-1197 tion. When TEVMON reached the alarm state, the bias voltages of the silicon 1198 detector were turned off automatically. 1199

The fast reacting hardware protection systems, the beam condition moni-1200 toring (BCM), consisted of four Beam Loss Monitors (BLMs). These were two 1201 ionization chambers on the east and two on the west side of the detector, about 1202 4.3 m from the nominal interaction point (I.P.) and at a radius of about 20 cm 1203 from the beam axis. The location of the BLMs from the I.P. was necessary due 1204 to their size, which made it impossible to put them inside the detector. The 1205 BLMs were read out every 210 μ s (10 beam revolutions), and a circular buffer of 1206 2048 measurements was kept. The BLMs monitored the radiation accumulated 1207 over the last minute and the radiation rate. An accumulated dose greater than 1208 19 rads (0.19 Gy) over the previous minute would issue an *integrated dose alarm*, 1209 whereupon the shift crew would pass on the alarm to the Tevatron operators 1210 and adjustments to the Tevatron operation would be made. If the radiation rate 1211 exceeded 12 rads/s (0.12 Gy/sec), the radiation abort alarm would fire, where-1212 upon the Tevatron would automatically issue an abort and the beams would be 1213 dumped. 1214

A closer examination of beam incidents showed the BLMs lacked the timing 1215 resolution and dynamic range to foresee the conditions leading to an *radiation* 1216 abort. A system of smaller sensors, closer to the beam and with a faster read-1217 out system, could abort the beam more rapidly to improve the safety of the 1218 CDF silicon detector. This led to the installation of a diamond-based BCM 1219 system [37]. A total of thirteen diamond sensors were installed in the CDF de-1220 tector, at the locations indicated in Fig. 12. Two groups of four diamond-based 1221 sensors were located inside the tracking volume, with each group mounted in a 1222 support structures at a distance of 1.7 m from the nominal I.P., arranged as the 1223 sides of a 4 cm by 4 cm square. Five more diamond-based sensors were installed 1224 outside the tracking volume, on the previous BLM system support structure; 1225 two diamonds on the west side and three on the east side. 1226

The BCM system was configured to abort the Tevatron beams when at least four diamond sensors measured a current of at least 500 nA and the CDF solenoid was fully energized, as the diamond dark current was affected by the external magnetic field. These settings were determined from a six-month study period to optimize the thresholds, and allowed quick response to potential beam incidents, while minimizing the number of false aborts.



Figure 12: The locations of the diamond-based BCM system in the CDF detector. The picture shows the upper hemisphere of the CDF detector. The proton beam circulated from left-to-right along the horizontal axis, colliding with the anti-proton beam that circulated in the opposite direction. The collision occurred at the interaction point, indicated by "I.P." in the figure. A pair of four red dots, symmetrically placed on either side of the I.P., indicate the sensors inside the tracking volume, and the red dots further away from I.P. along the beamline indicate sensors outside the tracking volume.

1233 7. Sensor Readout Calibration

The dynamic pedestal subtraction (DPS) feature of the SVX3D chip used a fraction of all channels to calculate a real time, common pedestal set to correspond to zero collected charge. This algorithm ensured that most channels have a mean pedestal close to zero, but some channels still exhibited a pedestal significantly different than the DPS pedestal.

The calibration algorithms measured the mean pedestal and noise for each 1239 electronics channel on every chip. These values were determined from dedicated 1240 calibration runs, in which every channel was read out, taken with colliding 1241 beams at low ($\leq 50 \times 10^{30} \text{ cm}^{-2} \text{s}^{-1}$) instantaneous luminosity. A standard 1242 silicon calibration included two runs: one with DPS turned off and one with 1243 DPS on. The analysis of data from these runs started with accumulation of 1244 the ADC pulse height distributions for every strip in the silicon system. The 1245 calibration algorithms used the DPS-off pulse height distribution to infer the 1246 DPS-on distribution. An example of the pulse height distributions from one 1247 silicon strip in DPS-off and DPS-on calibration runs is shown in Fig. 13. 1248

The DPS-on pulse height distributions alone are not sufficient for estimation of the DPS-on pedestals and noise. To deduce these pedestals, the software needed to simulate the effect of the DPS circuit using DPS-off data. The software required the number of channels above threshold before the integration counter begins. This value was determined for each chip during commissioning and an average value of 33 channels was found adequate for data taking.

After the pedestal and noise (width) of the ADC distributions were found for each channel using robust estimators, a program found channels to be flagged as bad, due to low occupancy ("dead") or high occupancy (noisy or "hot"). Noisy



Figure 13: Effect of Dynamic Pedestal Subtraction on pulse height distribution of a single channel in 1000 events. The DPS-off distribution is shown in blue, DPS-on is red, and the green histogram is an extrapolation of what the DPS-on distribution would be if negative ADC counts could be recorded. The peak at 0 ADC counts in the DPS-on distribution is suppressed by choice of scale.

channels were not included in the default offline clustering algorithm, but couldbe included in special studies.

Once bad channels were tagged and calibration constants calculated sepa-1260 rately for DPS-on and DPS-off operation, a series of calibration quality checks 1261 were performed. Calibration constants that changed dramatically were flagged 1262 for expert notification. Since the offline calibration runs were performed ap-1263 proximately twice per month, the configuration of ladders could change between 1264 calibrations. In these cases, the calibration framework mixed the DPS-on and 1265 DPS-off pedestals and noise constants as appropriate and wrote the relevant 1266 constants to the CDF database. The calibration constants were used for data 1267 reconstruction as well as detector simulation. 1268

1269 8. Detector Monitoring and Operations Support

The operation and maintenance of the silicon detectors required dedicated 1270 personnel and software for fast problem response. The CDF Silicon Group was 1271 comprised of approximately ten on-call experts who provided 24-hour support 1272 to the CDF operations group and performed regular maintenance to ensure 1273 optimal performance of the detector. The group was led by two sub-project 1274 leaders. Two experts were assigned to each of the following subsystems: DAQ, 1275 power supplies, and cooling. Another expert periodically performed calibrations 1276 of the detectors and ensured their quality. In addition, three to four experts 1277 provided online monitoring of the detector and gave prompt feedback to the 1278 group of any developing hardware problems. The group strived to optimize and 1279 automate most aspects of the silicon detector operations over the years. 1280

Many software packages were developed for detector operations and monitoring. They were broadly divided into three categories: stand-alone java applications used by the shift crew, scheduled jobs to acquire data on power supplies and the cooling and DAQ systems, and Perl-based CGI scripts that provided real-time information to the Silicon Group.

1286 8.1. Silicon Auto-Recovery

The SVX3D readout chips (see Section 3.3.1) required proper initialization 1287 sequence as soon as they were powered. The process of turning on power to 1288 the silicon detectors required synchronized actions in both the power supply 1289 control and the DAQ. Over time, a set of well established procedures to recover 1290 from common failure modes was developed. However these manual recovery 1291 procedures reduced the data-taking efficiency, especially when a large fraction 1292 of the detector channels needed to be turned on after failures, such as a power 1293 supply crate reset (see Section 4.3). 1294

In order to automate and speed up the recovery of power to the detector channels, a *Silicon Auto-Recovery* (SAR) software tool was developed. SAR detected channels that lost power during data-taking and sent a request to the power supply control to turn these channels back on. Once the power to the chips was restored, SAR took the corresponding FIB through the initialization process which also initialized the chips. During this process, data taking was suspended. After automating both the power supply crate reset and recovery, the average experimental downtime due to lost communication (see Section 4.3) with the power supply crates was reduced from 10 minutes down to less than 5 minutes.

1305 8.2. SVXMon

SVXMon was the monitoring application used for both online and offline
 diagnostics of the CDF silicon detector problems. It ran continuously during
 data taking as part of a set of CDF monitoring applications. It accumulated
 various statistics and presented a coherent set of silicon performance plots to
 the shift crew. On special occasions, it sent automated requests to reinitialize
 DAQ components showing problems.

SVXMon was a highly configurable program capable of presenting both very 1312 general and very detailed views of the silicon data. For each silicon strip, SVX-1313 Mon accumulated the number of hits and pulse height distribution. These were 1314 used to create plots of occupancies, average pulse heights, distribution shapes, 1315 etc., with various degrees of detector granularity. The monitoring application 1316 had a large number of configuration parameters which evolved over time to op-1317 timize the information useful to detect and understand error conditions in the 1318 silicon detectors. 1319

1320 8.3. IMON

IMON was an application used to monitor currents in the silicon detectors. *IMON* displayed each ladder of the detector as a set of color-coded boxes (one
for each channel of the ladder). If the measured current was within a pre-set
range, then the box showed up green. If it was just outside the good range,
it showed up yellow. If it was far outside that range, it turned pink.⁴ When a
ladder turned pink, it alerted the shift crew so they could take action.

As the sensors degraded due to exposure to radiation, they drew more current. Eventually, a sensor drew enough current to send it over the pre-defined "good" range; this was normal and simply required adjustment of the good range for that particular sensor by a member of the Silicon Group. A typical bias channel drew an additional 30 μ A of current for every 500 pb⁻¹ of delivered integrated luminosity. The currents drawn by the chip chains did not change. When one exceeded the normal limits, it typically needed to be reinitialized.

Although the concept for adjusting the bias current limits was simple, the actual procedure was tedious. Limits for the bias currents were adjusted and documented in a database. The rate of increase varied widely across the channels due to the sensor type, radiation exposure, and other causes. With close to 500 bias channels, 25–50 adjustments were made every week. Changing the limits by hand could take several minutes per channel. For bias channels which had

⁴Other colors were used to indicate ladders which had tripped, turned off, had lost communication or were ignored by the DAQ.

increases consistent with normal aging, the limits were adjusted by a monitoring
program. After automatic adjustment software was made operational, it took
care of approximately 95% of the limit adjustments, drastically cutting down
the workload of the Silicon Group.

1344 8.4. ADCMon

The Silicon Group had the responsibility to ensure good quality of the data 1345 collected by the silicon detectors. ADCMon was an application developed to 1346 ease that task. ADCMon read the raw information recorded by the DAQ and 1347 provided the distributions of charge in ADC counts for each silicon ladder. Two 1348 different versions of ADCMon were implemented: online and offline. The online 1349 version operated in the CDF control room during data taking and provided data 1350 to SVXMon. It provided the charge distribution of the last 500 events, as well 1351 as the statistics accumulated during the entire run of data taking. The offline 1352 version was executed with a delay of less than one day from the end of the 1353 run and was useful to understand long term behavior of the silicon ladders. It 1354 generated a table of histograms representing the charge distribution for events 1355 of a given run in comparison with a reference run. It also provided information 1356 about the percentage of bit errors in digital transmission of data. 1357

Optical data transmission bits could permanently get stuck in a high or low state due to radiation damage, cable or electronics malfunction, as described in Section 3.8.2. This could lead to a lower resolution of the charge distribution. Discrepancies in the shape of charge distributions or absence of data could be caused by a FIB or power supply failure. Severely underdepleted ladders could show an observable drop in the high end of the charge distributions. A visual evaluation of the offline results required 5–10 minutes per day.

1365 8.5. iFIX

Some components of the silicon detector needed to be monitored independent of data taking. A system to do this was developed based on the commercial automation software *Proficy HMI/SCADA iFIX*, licensed by GE Fanuc [38]. Data was stored at intervals on the order of a few seconds, with recent readings ranging from a few hours to a few days being displayed in the CDF control room. Older data was migrated to permanent storage. This information could be retrieved from iFIX computer nodes.

1373 8.5.1. Slow Control of Cooling System

An iFIX node was connected to the PLC system through a VME module 1374 to a Siemens SIMATIC 505 Crate, where the I/O modules resided (see Fig. 11 1375 in Section 5.2). Information from the cooling related devices was available in 1376 the iFIX software which provided displays of real-time readings of the devices 1377 (temperature sensors, pressure gauges, flowmeters, valves, etc). Changes to 1378 parameters of selected devices could be made through this system. The system-1379 wide and sub-component interlock status were also displayed. In particular, the 1380 most valuable quantities monitored in this system were the temperatures of the 1381 cooling lines inside the detector, as well as the flows and pressures. 1382

1383 8.5.2. Audible Alarm System

Alarm conditions were defined for selected variables, such as the cooling variables which could potentially trigger the interlocks. In the case of temperatures,
pressures and flows, low and high warning and alarm limits were defined. Other
variables in the alarm list included the high voltage and trip status of power
supplies. Any alarm going off was followed by an audible voice alarm.

1389 8.5.3. Monitoring of Rack Modules

The status of the AC power to the racks hosting the FIB and CAEN crates in the collision hall was monitored, and remote power cycling of racks was possible. In addition, monitoring and alarming on low-voltage status was available for small devices in the racks, such as fans inside the crates. This was also true for the racks hosting the VRB modules outside the collision hall. We also monitored the power supply output voltages for the VRB and FIB crates.

1396 8.5.4. Reset of Silicon Power Supplies

The automatic reset of CAEN power supply crates (explained in Section 4.3) was monitored in the iFIX system. Additionally, the silicon operations team could manually reset any power supply crate from this system.

¹⁴⁰⁰ 9. Monitoring Radiation Damage Effects

1401 9.1. Depletion Voltages

Periodically, the depletion voltage of each sensor was measured to monitor the radiation effects on the sensor, and the operating voltage increased to ensure that the sensors remained fully depleted. The operational definition of depletion voltage for the CDF silicon detectors was the bias voltage at which the charge collection saturates. Specifically, the voltage at which the charge collected was 95% of the maximum value. Operating at bias voltages larger than a depletion voltage defined this way ensured the best detector performance.

Two different methods to measure the depletion voltage were used: the *noise scan* was used for double-sided sensors that had not undergone type inversion, and the *signal scan* was used for all sensors. In each case, the bias voltage was changed and either the signal from charged tracks or the noise in the sensor was measured. The results of both methods are presented here in the context of operating the detector. Further discussion of the observed effects of radiation damage in the sensors is reserved for a future article dedicated to this topic.

1416 9.1.1. Noise Scans

¹⁴¹⁷ The noise scan measured the average noise for each ladder as a function of ¹⁴¹⁸ bias voltage. For each bias voltage setting, data were taken in read-all mode ¹⁴¹⁹ and the ADC count distribution for each strip was recorded. For each ladder, ¹⁴²⁰ the noise was determined by taking the RMS of the ADC distribution for each ¹⁴²¹ strip and then averaged over the strips on the p-side $(r-\phi)$ and the n-side (r-z)¹⁴²² separately.



Figure 14: Noise scan measurements for a single ladder from layer 1 of SVX-II at four different integrated luminosities (given in fb^{-1}). The blue squares are the measured noise on the n-side. The pale green triangles are the measured noise on the p-side of the sensor. The extracted depletion voltage is indicated with a vertical line.

The depletion voltage for each ladder was determined by fitting the n-side
 noise as a function of the bias voltage to a sigmoid function

$$noise = A + \frac{B}{1 + \exp\left[-C(V - D)\right]} \tag{1}$$

where A, B, C and D are fit parameters and the variable V is the bias voltage. The depletion voltage was identified as the voltage at which the function is equal to the sum of lower plateau of the sigmoid function and 5% of the height of the fitted sigmoid function, or $V_{dep} = D(ln19)/C$.

Noise scans for a typical ladder taken at different integrated luminosities are
shown in Figure 14. In the early scans, the separation between the two noise
levels for the n-side was large, and the depletion voltage was easily determined,
as seen from Figure 14(a). As the sensor became irradiated, the underdepleted



Figure 15: The average depletion voltage determined from noise scans is plotted for the Hamamatsu sensors in SVX-II (see Table 1) as a function of radiation dose.

noise level decreased while the depleted noise level increased, and it became in-1433 creasingly difficult to determine the depletion voltage using this method. Specif-1434 ically, noise scans where the two noise levels of the n-side were separated by less 1435 than 0.2 ADC counts did not give a reliable determination of the depletion volt-1436 age. Figure 14(d) shows the measured noise after inversion of the sensor, for 1437 which the p-side noise and n-side noise have similar behavior. After the inver-1438 sion, the overall noise level increased with radiation dose as expected, but the 1439 shape of the curves remained the same. 1440

The noise scan method was used to monitor the depletion voltage before 1441 the inversion of the sensors. Figure 15 shows the average depletion voltage for 1442 ladders in layers 0,1, and 3. Noise scans where the two noise levels of the n-side 1443 were separated by less than 0.2 ADC counts are not included in the plot. In 1444 order to compare the different layers, integrated luminosity was converted to the 1445 equivalent dose of the radiation field measured inside the CDF detector with 1446 over 1000 thermal luminescent dosimeters in 2001 [39], summarized in table 2. 1447 The behavior of the three different layers was remarkably consistent considering 1448 that the integrated dose received by the layer depends on the distance from the 1449 interaction region. The sensors from layers 2 and 4, which are from a different 1450 manufacturer than the other layers, were not included in this analysis because 1451 they developed complicated noise profiles and the simple data analysis described 1452 above did not give reasonable quantitative results and signal scans were used 1453 instead to monitor the depletion voltage. 1454

1455 9.2. Signal Scans

The signal scan provided the best evaluation of the depletion voltage, and in many cases the only one. The charge collected by the sensor increased with increasing bias voltage as the depleted region in the sensor grew, until the sensor was fully depleted and the charge saturated. The scan had to be performed with

	r(cm)	$dose/L (kRad/fb^{-1})$
L00 narrow	1.35	994 ± 199
L00 wide	1.62	756 ± 151
SVX-L0	2.54	385 ± 77
SVX-L1	4.12	186 ± 37
SVX-L2	6.52	94 ± 19
SVX-L3	8.22	66 ± 13
SVX-L4	10.10	49 ± 10

Table 2: The radiation dose per unit luminosity measured by the TLDs in the CDF tracking volume [39], extrapolated to the location of the individual silicon layers .

colliding beams and required approximately two hours per layer. To minimize
the amount of lost physics data, the scans were done when the instantaneous
luminosity was low.

¹⁴⁶³ Data were acquired with a specific trigger selecting collision events containing ¹⁴⁶⁴ at least two tracks. From these events, tracks traversing the silicon layer under ¹⁴⁶⁵ study were identified using the COT and remaining silicon layers. If one and only ¹⁴⁶⁶ one cluster existed within 150 μ m of the location where the extrapolated track ¹⁴⁶⁷ crossed a sensor, the total charge of that cluster was recorded in a histogram. ¹⁴⁶⁸ A reasonable fit result required at least 1,000 tracks per ladder per bias voltage ¹⁴⁶⁹ setting, with additional tracks per point needed below 20 V.

The distribution of cluster charges was fit to the convolution of a Landau 1470 function and a Gaussian function in the region around the peak. The upper 1471 plots of Figure 16 are examples of this distribution at two different bias voltages. 1472 The most probable value of the fitted function was plotted as a function of bias 1473 voltage, and these points were fitted to a sigmoid function of the same form as 1474 Equation 1. The measured depletion voltage was the bias voltage at which the 1475 function value is 95% of the total charge is collected, or $V_{dep} = 0.95 * (A + B)$. 1476 An example is shown in Figure 16(c). Also shown on this plot is the efficiency, 1477 defined as the fraction of tracks for which a cluster is found. Due to the limited 1478 data samples of these special runs, the track selection was quite loose, and 1479 the absolute value of this efficiency does not reflect normal sensor performance 1480 during data taking. 1481

The non-zero value of the cluster charge for bias voltages below 10 V was a 1482 measure of the effective clustering threshold for that ladder. All strips of L00 1483 were read out every event, while for SVX II and ISL, only strips above 9 ADC 1484 counts plus the neighboring strip on either side were readout. The standard 1485 offline clustering threshold was calculated from the strip noise measured in the 1486 sensor readout calibrations (Section 7) for the strips taking part in the cluster. 1487 This combined with the offline clustering thresholds sculpted the cluster charge 1488 distributions at low bias voltages. Although the initial rise of the cluster charge 1489 was hidden by the clustering threshold, the increasing efficiency indicated in-1490 creasing mean cluster charge as more and more clusters were found above the 1491 threshold. Because the strip noise increased with radiation dose, these cluster-1492

ing thresholds creeped upward with integrated luminosity, and the signal scans
allowed them to be monitored. Figure 16(d) shows the evolution with luminosity of this sensor's depletion voltage. The points beyond the inversion point
were fit with a line.

¹⁴⁹⁷ Close monitoring of L00 and the inner layers of SVX was essential after ¹⁴⁹⁸ inversion to keep the operating bias voltages above the depletion voltage. Oper-¹⁴⁹⁹ ating voltages were increased on a sensor by sensor basis after extrapolating the ¹⁵⁰⁰ linear trend in the measured depletion voltages several months into the future.

Figure 17 shows the linear fitss for the individual L00 ladders as gold or 1501 red lines and the average over all the ladders as a black line and blue points. 1502 The predicted depletion voltages for all L00 ladders lie well below the power 1503 supply limit of 500 V and the sensor breakdown region that starts at 650 V, 1504 and they were fully depleted through the end of Run II. Figure 18 shows the 1505 linear fits for the $r-\phi$ side (p-side) of the first layer of SVX-II (SVX-L0). The 1506 fitss for individual ladders are shown as red lines and their average as a black 1507 line. The blue points are the average measured depletion voltage for all ladders. 1508 The power supply limit for these sensors is 250 V and sensor breakdown was 1509 expected in the range 170-270 V, indicated with a shaded region. 1510

In agreement with the projections, roughly one third of the SVX-L0 ladders 1511 were not fully depleted for an operating voltage of 165 V at the end of Run II. 1512 The performance of these underdepleted ladders was only slightly compromised: 1513 the charge collected on the p-side was reduced, while the charge collected on the 1514 n-side was unaffected. Because of the risk of damage to the sensor, we decided 1515 not to operate any ladders above 165 V until the hit efficiency of the ladder 1516 began to decrease. Only one ladder reached this condition by the end of the 1517 run. That is, the hit efficiency of all but one of the underdepleted ladders was 1518 still maximal at the end of the run despite the reduced charge collection on the 1519 $r-\phi$ side (p-side). 1520

¹⁵²¹ 9.3. Surprises in the Behavior of Irradiated Sensors

In the traditional model for the electric field in a reverse-biased silicon sensor, the field increases linearly through the bulk when the bias voltage is applied. There is however evidence that trapped charge in heavily irradiated sensors dramatically affects this simple picture of the field inside the sensor. In CDF, we have observed evidence that, after irradiation, the field was non-uniform and extended from both sides of the sensor. This resulted in a much longer lifetime for SVX-L0 operating with *safe* bias voltages than had been anticipated.

In undamaged CDF sensors, the electric field was highest at the p-side of 1529 a reverse biased pn diode junction, and decreased linearly through the bulk 1530 material. At bias voltages less than the depletion voltage, the electric field at 1531 the n-side was zero and essentially no signal was induced in the n strips as 1532 particles passed through the sensor. The general understanding of radiation 1533 damage to silicon sensors when the CDF detector was built (summarized in the 1534 Hamburg model[40]) was that radiation induced crystal damage made the bulk 1535 material increasingly more p-type. At sufficiently high dose, the n-type bulk 1536 material was expected to become effectively p-type (this is referred to as type 1537



Figure 16: The upper plots show the measured cluster charge distribution for a single L00 ladder at a bias voltage of 30 V (a) and 130 V (b) after 4 fb⁻¹ of integrated luminosity. Plot (c) shows the peak of the cluster charge distribution (red circles) and the efficiency (blue squares) as a function of bias voltage. The dashed line indicates the depletion voltage extracted from the sigmoid fit. Plot (d) shows the measured depletion voltage for this ladder as a function of integrated luminosity, and the linear fit used to extrapolate to higher luminosity values.



Figure 17: Summary of depletion voltage measurements and fits for L00 wide ladders (left) and narrow ladders (right).

inversion) and the junction side of the detector was expected to move from the p-side to the n-side. After type inversion, the electric field in the sensor was expected to be highest at the n-side diode junction and to decrease linearly through the bulk material. It was expected that essentially no signal would be recorded on the p-side at bias voltages less than the depletion voltage.

This behavior is now understood to be a consequence of the properties of 1543 damaged silicon with an applied bias voltage. In heavily irradiated silicon, 1544 the trapping of leakage current charge carriers dramatically affects the electric 1545 field inside the sensor. Leakage current is generated approximately uniformly 1546 throughout the thickness of the sensor. Electrons carry charge towards the n-1547 side and holes carry charge towards the p-side. This means that the density 1548 of moving electrons is highest near the n-side and the density of moving holes 1549 is highest near the p-side. Because the equilibrium number of trapped charges 1550 depends on the density of moving charges as well as trapping probabilities and 1551 trap lifetimes, the density of trapped electrons is highest near the n-side of the 1552 sensor and the density of trapped holes is highest near the p-side of the sensor. 1553 These trapped charges create an electric field with maxima at both sides of 1554 the sensor. The importance of trapped charges to the static field in heavily 1555 irradiated sensors was pointed out by Eremin, Verbitskaya, and Li in 2002[41]. 1556 Swartz, et al. have tuned a two trap model to fit CMS pixel beam test results, 1557 including temperature dependence[42]. 1558

The data from the signal scans taken after significant radiation exposure are consistent with an electric field peaking at both faces of the sensor, and clearly inconsistent with the naive expectation of a linearly decreasing field with a single maximum at the n-side. Figure 19 shows the signal scan data delivered luminosities of 0.3 fb^{-1} (above) and 6.9 fb^{-1} (below) for a typical sensor in SVX-L0. Because the signal was induced primarily by the motion of charge carriers in the depleted region adjacent to the electrode, the measured cluster charge for a



Figure 18: Summary of depletion voltage measurements and fits for the $r-\phi$ side or p-side (left) and the r-z side or n-side (right) of SVX-L0 sensors.

particular voltage was a measure of the size of a possible depleted region adjacent 1566 to the electrode. Because of the readout thresholds for the SVX sensors, clusters 1567 below 10-15 ADC counts are not detected. However, the fraction of tracks with 1568 clusters above this threshold, shown as blue squares in Figure 19, increased as 1569 the average charge collected increased. The upper measurement in Figure 19 was 1570 done when the sensor was only slightly irradiated. The charge collection began 1571 at smaller voltages on the p-side than the n-side, compatible with a depleted 1572 region that began at the pn junction and grew towards the n-side electrode as 1573 the bias voltage increases. The lower measurement was done after 6.9 fb^{-1} of 1574 luminosity, and the charge collection began at similar bias voltages for each 1575 side and increased similarly with increasing voltage. This latter behavior was 1576 compatible with an electric field that had two maximums, one at either face of 1577 the sensor, creating two depleted regions that started at either face and grew 1578 toward the center of the sensor as the bias voltage increased. Similarly, for the 1579 p-side of a single sided L00 sensor after 4 fb^{-1} of luminosity (post-inversion), 1580 Figure 16(c) shows an early onset and gradual increase of charge collection, 1581 again consistent with a doubly peaked electric field. 1582

The unexpected electric field behavior had an important consequence for the 1583 longevity of the CDF silicon detector. The SVX-L0 ladders could be operated 1584 in a slightly underdepleted state with only a small loss in charge collection and 1585 no loss in hit efficiency for a short time after the depletion voltage exceeded 1586 the maximum safe operating voltage. Because the b-tagging efficiency (Sec-1587 tion 10.2) of the detector was insensitive to a small loss in charge collection in a 1588 fraction of the SVX-L0 sensors, it was decided to operate these sensors slightly 1589 underdepleted instead of risking damage at higher bias voltages. 1590



Figure 19: The cluster charge (circles) and efficiency (squares) as a function of bias voltage for the p-side $(r-\phi, \text{ left})$ and n-side (r-z, right) of a typical SVX-L0 sensor. The dashed line indicates the depletion voltage extracted from the measurement. The upper plots contain data taken after 0.3 fb⁻¹ of delivered luminosity, the lower plots data taken after 6.9 fb⁻¹ for a sensor that inverted around 1.5 fb⁻¹.



Figure 20: Measured signal-to-noise ratio for L00 (left), the $r-\phi$ side of SVX-II (left) and the r-z side of SVX-II (right).

1591 9.4. Signal-to-Noise Ratio

¹⁵⁹² During Run II, the signal-to-noise ratio (S/N) of L00 and SVX-II sensors ¹⁵⁹³ were monitored using well-measured tracks from events selected by the low ¹⁵⁹⁴ momentum dimuon trigger. The signal *S* was defined as the summed charge of a ¹⁵⁹⁵ cluster of strips associated with a track and corrected for path length. The noise ¹⁵⁹⁶ for individual strips was measured during special calibration runs performed bi-¹⁵⁹⁷ weekly with beam, as described in Section 7. The noise of a cluster *N* was ¹⁵⁹⁸ defined as the average noise of the individual strips belonging to the cluster.

Figure 20 shows the average measured S/N ratio for L00 and SVX-II, separately for the r- ϕ and r-z sides. All ladders that operated consistently well throughout Run II are included, corresponding to roughly 75% of all ladders. As expected, the S/N ratio decreased more quickly for L00 and SVX-L0 since they were closer to the interaction point and suffered from more radiation damage. The dip in S/N values for L00 and SVX-L0 near 8fb⁻¹ corresponded to a period of slight underdepletion.

We observed plateaus in the ratios in the L00 and SVX-L0 S/N ratios be-1606 ginning at 5 fb^{-1} and 8 fb^{-1} , respectively. To verify that the leveling-off was 1607 not an artifact of the averaging, the S/N curves for the individual ladders were 1608 investigated. Figure 21 shows the S/N trends for the overall L00 average and 1609 for three typical ladders whose S/N values are close to (a) the overall L00 av-1610 erage, (b) the plus-one RMS variation with respect to the overall average, and 1611 (c) the minus-one RMS variation with respect to the overall average, where the 1612 RMS was defined as the spread of S/N values for the ladders used in the aver-1613 age. As we observed a plateau-like feature for each ladder, we concluded that it 1614 was not due to an averaging artifact. The source of the plateau remains under 1615 investigation. 1616



Figure 21: Measured signal-to-noise ratio for the L00 average, and for three ladders that represent typical ladders close to the average, and close to the ± 1 RMS signal-to-noise values with respect to the average. The RMS represents the spread of signal-to-noise values for the various ladders included in the average.

¹⁶¹⁷ 10. Physics Performance of the Silicon Detector

Good performance of the silicon detectors was vital to the success of CDF's physics program. In this section we present some of the performance quantities which directly impact the results from analyses requiring silicon tracks or displaced secondary vertices found by SVT. Reported here are studies on the impact parameter resolution with and without L00, the b-tagging efficiency and the SVT efficiency.

1624 10.1. Impact Parameter Resolution

The impact parameter, d_0 is defined as the shortest distance in the $r-\phi$ plane 1625 between the beam line and the trajectory of the particle obtained from the track 1626 fit. The impact parameter resolution σ_{d_0} is a key performance indicator of the 1627 CDF silicon detector. This resolution affects identification of long-lived hadrons 1628 as well as the ability to study time-dependent phenomena, such as the mixing of 1629 $B_{\rm s}$ [31] and charm mesons [43]. The detector provided good impact parameter 1630 resolution. L00 improved the performance particularly for particles with low 1631 momentum or that passed through large amount of passive material [44]. 1632

1633 The resolution is parameterized as a function of the particle transverse mo-1634 mentum p_T as

$$\sigma_{d_0} = \sqrt{A^2 + (B/p_{\rm T})^2 + r_{\rm beam}^2},$$
(2)

where A is the asymptotic resolution parameter, and B is the multiple-scattering component. The finite beam size $r_{\text{beam}} = 32 \ \mu\text{m}$ accounts for the uncertainty in the location of the primary interaction.

Figure 22 shows the fitted widths of the cores of the impact parameter distributions for tracks with and without L00 hits as a function of the track $p_{\rm T}$.

Table 3: Fit parameters for the resolutions shown in Fig. 22. The definitions of the fit parameters are given in Equation 2. A fixed beam size, $r_{\rm beam} = 32~\mu m$, is assumed.

Track Category	$A \ (\mu m)$	$B~(\mu m)$
Hybrid, No L00	35.6 ± 0.6	77.9 ± 0.5
Hybrid, L00	25.1 ± 0.3	40.1 ± 0.3
No Hybrid, No L00	28.6 ± 0.3	35.5 ± 0.3
No Hybrid, L00	17.8 ± 0.2	28.4 ± 0.1

The inclusion of L00 enhances the impact parameter resolution at low momen-



Figure 22: Impact parameter resolutions for tracks as a function of track $p_{\rm T}$. Both plots show the resolutions for tracks before and after the addition of L00 hits. The plot on the left shows the resolutions for tracks that pass through readout hybrids which are mounted on some of the sensors, and the plot on the right shows the performance for tracks that do not pass through hybrids. These plots include the $r_{\rm beam}^2$ term in Equation 2.

1640

¹⁶⁴¹ tum. For tracks that pass through the electrical readout hybrids, the impact ¹⁶⁴² parameter resolution is somewhat degraded.

Table 3 lists the fit parameters for the four classes of tracks in Fig. 22. The addition of L00 hits to tracks does not have much effect on the asymptotic resolution at high momentum. Furthermore, knowledge of the impact parameter is limited by the beam size unless a primary interacting vertex is reconstructed with many high-momentum tracks.

1648 10.2. b-Tagging Efficiency

Many of the physics goals of the CDF experiment rely on the identification 1649 of weakly decaying bottom hadrons. The mean lifetime of these hadrons is 1650 approximately 1.5 ps, and the mean decay length is order of a few millimeters. 1651 The fact that the weakly decaying hadrons have large boosts means that the 1652 particles from the decay travel in approximately the same direction as the parent 1653 hadron, with their kinematic distributions depending on the mass of the parent 1654 hadron. Precise measurement of the track positions allows tracks originating 1655 from displaced vertices to be distinguished from tracks that originate at the 1656 primary vertex. Most jets of hadrons produced in $p\bar{p}$ collisions do not contain 1657

bottom or charm hadrons, and very strong rejection of falsely tagged light-flavor
jets is another important figure of merit for the tracker.

CDF uses a displaced-vertex algorithm, SECVTX [45], to identify — or *b-tag* — secondary vertices that are significantly displaced from the beamline. It has two configurations, referred to as "loose" and "tight", which refer to the track and vertex requirements used to form the displaced-vertex candidates. With the loose requirements, more displaced vertices from heavy hadron decay are identified than the tight requirements, but with a higher rate of falsely tagged light-flavor jets.

The assignment of silicon hits to tracks has a large impact on the efficiency 1667 of the algorithm to identify the decays of heavy hadrons, as at least two well-1668 measured tracks are required to form a displaced vertex, and the presence of hits 1669 in multiple silicon layers in the inner tracking volume improves the chances of 1670 finding that the vertex is significantly displaced from the primary. The tails in 1671 the impact parameter resolution — due to hard nuclear collisions with detector 1672 material, multiple scattering, and mis-assigned hits in the silicon detector and 1673 COT — determine the false tag rate. 1674

The efficiency of the algorithm to identify heavy hadrons increases with the 1675 hadron momentum. The efficiency is not measured directly since not all hadron 1676 decay products are reconstructed; instead it is parameterized as a function of 1677 the transverse energy $E_{\rm T}$ of the jet and shown in Figure 23. The efficiency 1678 rises with momentum because the tracks that result from the decay are better 1679 measured at higher energy, and the decay flight distance is also longer. At very 1680 high $E_{\rm T}$, the tagging efficiency drops, as tracks begin to share hits, with the 1681 jets becoming more collimated. Figure 23 also shows the b-tag efficiency as a 1682 function of the pseudorapidity, $|\eta|$, of the jet. Jets at higher pseudorapidity pass 1683 through more material and have fewer COT hits, reducing the tag efficiency and 1684 raising the false tag rate as shown in Figure 24. At very high pseudorapidity, 1685 the loss of tracking efficiency in the COT also reduces the false tag rate. 1686

At high instantaneous luminosities, the average occupancy of the silicon de-1687 tector and the inner layers of the COT rises. This leads to increased chance of 1688 assigning noise hits to the tracks as well as missed COT hits due to ambiguity 1689 in resolving many overlapping tracks. As a result, at higher instantaneous lumi-1690 nosities, the b-tag efficiency drops slightly and the fake tag rate rises. The b-tag 1691 efficiency is shown in Figure 25 as a function of the number of reconstructed 1692 primary vertices per beam crossing, which is more directly related to the track-1693 ing occupancy than the instantaneous luminosity. The *b*-tagging performance is 1694 remarkably robust at high luminosities due to the high granularity of the silicon 1695 detector covering the low radii tracking region. 1696

1697 10.3. SVT Efficiency Study

Aging of and radiation damage to the silicon detector resulted in increased noise and reduction of the level of the signal (see Section 9.4). These factors degraded the performance and efficiency of the SVT (see Section 3.1.1). A study was performed during the Tevatron run to measure the SVT efficiency as a function of total integrated luminosity and estimate any potential impact on



Figure 23: Efficiency of the displaced vertex *b*-tagger, as functions of jet $E_{\rm T}$ and jet pseudorapidity, for two configurations of the *b*-tagger. The efficiency is obtained from tagging jets which have been matched to *b* quarks in Monte Carlo top quark decays, multiplied by data/MC scale factors.



Figure 24: Probability of non-*b*-jets to be *b*-tagged for the displaced vertex *b*-tagger, as functions of jet $E_{\rm T}$ and jet pseudorapidity, for two configurations of the *b*-tagger. The probabilities have been measured from inclusive jet data.

physics analyses. Starting from the measured level of signal and noise in the silicon detector for a reference data sample at 3 fb⁻¹, simulated samples were produced by applying extrapolations of the signal and noise up to 8 fb⁻¹. Each of the samples was used as input to SVT simulation software to estimate the efficiency of the trigger at the corresponding integrated luminosity. Figure 26 shows the prediction of the SVT efficiency as a function of total integrated luminosity for four (open circles) and all five (closed circles) layers of SVX-II.

¹⁷¹⁰ A decrease of SVT efficiency of about 4% was predicted between 3-8 fb⁻¹, ¹⁷¹¹ while the impact of losing an SVX-II layer was about 13%.

1712 **11. Summary**

The CDF silicon detector, consisting of the SVX-II, ISL, and L00 components, was designed to withstand only 2-3 fb⁻¹ of integrated $p\bar{p}$ collision luminosity and was expected to be replaced in 2004 by an upgrade. It ran successfully for over 10 years, through 2011, and was exposed to about 12 fb⁻¹ of



Figure 25: Efficiency of the displaced vertex *b*-tagger, as a function of the number of reconstructed $p\bar{p}$ collision vertices per beam crossing, for two configurations of the *b*-tagger. The efficiency is obtained from tagging jets which have been matched to *b* quarks in Monte Carlo top quark decays, multiplied by data/MC scale factors.



Figure 26: Prediction of the efficiency of SVT as a function of total integrated luminosity. Closed black circles show the efficiency when only four layers of SVX-II are used by the SVT algorithm; empty red circles show the efficiency including all five layers.

integrated luminosity. About 90% of its ladders took data with high efficiency 1717 until the end of Tevatron Run II. This was an unprecedented feat compared to 1718 any silicon detector in the same category prior to it. It was also the first silicon 1719 detector system to be incorporated into a hardware trigger to identify tracks 1720 from secondary vertices. It provided precise measurements of the trajectories of 1721 charged particles which were important to identify and measure heavy-flavored 1722 hadrons, which in turn were crucial to CDF's physics program, including top 1723 quark, b hadron, and Higgs boson physics. 1724

The detector consisted of about 722,000 readout channels, with approximately 500 independent ladders, which required voltages to bias the sensors as well as run the data acquisition electronics mounted on the detector. Elaborate data acquisition, trigger, cooling, and monitoring systems were required to collect the data used for analysis. The detector itself was located inside the drift chamber in a volume heavily congested with cabling, cooling pipes, and the beam pipe, that rendered it largely inaccessible for repair. Due to its inherent

complexity, the detector operations involved detailed procedures and required 1732 specially trained experts to execute them. Keeping up with the loss of experts 1733 and training new ones to replace them was one of the major challenges faced 1734 by the silicon operations team. In addition, inaccessibility of the detector re-1735 quired that every detector access be planned elaborately and well in advance 1736 to take advantage of the Tevatron shutdowns. Future experiments must take 1737 extra care in designing the accessibility aspects of their subsystems to avoid 1738 these situations. 1739

The silicon detector system had its share of failure modes, most of which were addressed during commissioning and the rest were mitigated during the operation of the detector. The most serious failure modes, those that required immediate response, such as power supply failures, cooling system failures, and unsafe beam conditions, had dedicated hardware and software systems designed to protect the silicon detector from damage.

Unanticipated failure modes and exposures to detector damage became ev-1746 ident as Run II of the Tevatron progressed. These had been addressed with 1747 hardware modifications, monitoring, review, and improved operational proce-1748 dures to reduce the chance of damage to the detector. For example, the Lorentz 1749 force on bond wires perpendicular to the magnetic field, connecting one side 1750 of a ladder to another, on rare instances caused the wires to vibrate at their 1751 mechanical resonant frequency and eventually break (Section 3.6). A hardware 1752 device was devised and installed to stop data acquisition when the trigger system 1753 requested readouts at high frequencies and at regular intervals. Another issue 1754 involved spontaneous energizing of the kicker magnets or separators sparking at 1755 unexpected times, which steer the beams near the silicon detector and caused 1756 damage to it due to the acute radiation dose (Section 6.1.2). The addition of 1757 a collimator near CDF and improvement to the high voltage conditioning of 1758 the separators had minimized the effect of such incidents on the silicon detec-1759 tor. Careful monitoring of beam conditions, automatic ramp-down of the bias 1760 voltage in case of bad beam conditions and beam abort requests from the dia-1761 mond sensors had also protected the silicon detector from damage due to beam 1762 incidents. 1763

Certain electronic components necessary for the functioning of the silicon 1764 detector were located in the collision hall. Radiation caused temporary and 1765 permanent failures of data acquisition electronics, particularly FPGAs (Sec-1766 tion 3.8.1). The power supplies were also susceptible to radiation-induced fail-1767 ures (Section 4.3). Many of the temporary failures could be addressed simply by 1768 resetting and re-initializing the affected components, and these procedures were 1769 highly automated so that the reset and recovery to the nominal data-taking 1770 configuration resulted in a minimum of downtime. Permanent failures of col-1771 lision hall electronics typically required short accesses to replace the affected 1772 components. A sufficiently large pool of spares was kept on hand to maintain 1773 a high availability of the detector. Many of the components were repaired at 1774 Fermilab, and others required sending equipment back to the manufacturer. 1775

The cooling system for SVX-II and L00 worked remarkably well, while that of ISL experienced higher failure rates (Section 5). The initial epoxy blockages

were cleared with laser light guided inside the small cooling tubes with fiber 1778 optics. A later incident stemming from acidified ISL coolant caused leaks in the 1779 piping cooling the portcards. These leaks were sealed with epoxy from inside the 1780 pipes as the outside was inaccessible. The ISL coolant was returned to distilled 1781 water, as in early running phase, and care was taken to monitor and respond 1782 rapidly to changes in the cooling system. Nonetheless, as the system aged, leaks 1783 in the piping became larger. These did not impact the operation as the coolant 1784 ran below atmospheric pressure. 1785

The unexpectedly high longevity of the silicon detector, which came as a 1786 welcome surprise, is in part due to the slow aging of the sensors as radiation dose 1787 was accumulated (Section 9). The inner layers of the detector type-inverted as 1788 expected. The depletion voltage, signal response and noise behaved as expected 1789 also after type inversion. There was evidence that the electric field was not a 1790 linear function of the position within the sensor, but instead strengthened near 1791 the p+ and n+ implants. This created two depletion regions, one on either 1792 side of an underdepleted bulk. Sensors that were not fully depleted at the end 1793 of Run-II still provided usable data on both sides of the sensor, with slightly 1794 reduced charge collecton on the p-side. 1795

As a result of to its size and complexity, the CDF silicon detector required a 1796 dedicated team of experts to operate and maintain it, ensuring the continuous 1797 harvest of high quality data. Despite the challenges from a prolonged run and 1798 the gradual reduction of spares and experts toward the end of Run II, the 1799 data taking was concluded successfully due to extensive efforts on procedure 1800 automation and diligent monitoring of every subsystem. Sufficient experience 1801 with detector aging, operational failure modes and their mitigation gained along 1802 the way ensured good performance during the final years of Tevatron running 1803 at high luminosity. Many profound successes of the CDF physics program were 1804 the direct result of the high quality data provided by the silicon detector and 1805 the dedicated displaced vertex triggers based on it. 1806

1807 12. Acknowledgements

The authors would like to thank Dr. D. Christian and Dr. T. Zimmerman 1808 of Fermilab for useful discussions on radiation damage in silicon detectors and 1809 SVX3D chip functionalities, respectively. This work would not have been pos-1810 sible without a strong support by the CDF operations management and the 1811 spokespersons. We also thank the Fermilab staff and the technical staffs of the 1812 participating institutions for their vital contributions. This work was supported 1813 by the U.S. Department of Energy and National Science Foundation: the Ital-1814 ian Istituto Nazionale di Fisica Nucleare; the Ministry of Education, Culture, 1815 Sports, Science and Technology of Japan; the Natural Sciences and Engineering 1816 Research Council of Canada; the National Science Council of the Republic of 1817 China; the Swiss National Science Foundation; the A.P. Sloan Foundation; the 1818 Bundesministerium für Bildung und Forschung, Germany; the Korean World 1819 Class University Program, the National Research Foundation of Korea; the Sci-1820 ence and Technology Facilities Council and the Royal Society, UK; the Russian 1821

Foundation for Basic Research; the Ministerio de Ciencia e Innovación, and Programa Consolider-Ingenio 2010, Spain; the Slovak R&D Agency; the Academy
of Finland; and the Australian Research Council (ARC).

1825 References

- [1] CDF Collaboration, The CDF II Detector Technical Design Report,
 FERMILAB-Pub-96/390-E (1996).
- ¹⁸²⁸ [2] K. Anikeev *et al.*, B Physics at the Tevatron: Run II and Beyond, hep-¹⁸²⁹ ph/0201071v2 (2002).
- [3] TEVNPH (Tevatron New Phenomena and Higgs Working Group), CDF Collaboration, D0 Collaboration, Combined CDF and D0 Search for Standard Model Higgs Boson Production with up to 10.0 fb^{-1} of Data, FERMILAB-CONF-12-065-E, CDF-NOTE-10806, D0-NOTE-6303 (2012).
- [4] D. A. Toback, Run II searches for supersymmetry, AIP Conf. Proc. 753
 (2005) 373–382.
- [5] P. Azzi, Top quark measurements at Tevatron Run II, AIP Conf. Proc. 794
 (2005) 66–69.
- [6] T. Akimoto *et al.*, The CDF Run IIb Silicon Detector: Design, preproduction, and performance, Nucl. Instrum. Methods Phys. Res., Sect. A 556 (2006) 459 481.
- [7] P. Merkel, The CDF silicon detector upgrade and performance, Nucl. Instrum. Methods Phys. Res., Sect. A 501 (1) (2003) 1 6, Proceedings of
 the 10th International Workshop on Vertex Detectors.
- [8] C. S. Hill, Initial experience with the CDF layer 00 silicon detector, Nucl.
 Instrum. Methods Phys. Res., Sect. A 511 (1-2) (2003) 118 120, Proceedings of the 11th International Workshop on Vertex Detectors.
- [9] S. Hou, Experience with parallel optical link for the CDF silicon detector,
 Nucl. Instrum. Methods Phys. Res., Sect. A 511 (1-2) (2003) 166 170,
 Proceedings of the 11th International Workshop on Vertex Detectors.
- [10] G. Bolla *et al.*, Wire-bond failures induced by resonant vibrations in the CDF silicon detector, Nucl. Instrum. Methods Phys. Res., Sect. A **518** (1-2)
 (2004) 277 - 280, Frontier Detectors for Frontier Physics: Proceedings.
- [11] L. Miller, Status of the CDF silicon detector, Nucl. Instrum. Methods Phys.
 Res., Sect. A 518 (1-2) (2004) 281 285, Frontier Detectors for Frontier
 Physics: Proceedings.
- [12] C. S. Hill, Operational experience and performance of the CDF II silicon detector, Nucl. Instrum. Methods Phys. Res., Sect. A 530 (1-2) (2004) 1 – 6, Proceedings of the 6th International Conference on Large Scale Applications and Radiation Hardness of Semiconductor Detectors.

- [13] T. Nelson, The CDF Layer 00 detector, Int. J. Mod. Phys. A 16S1C (2001)
 1091–1093.
- [14] CDF Collaboration, SVXII simulation and upgrade proposal,
 CDF/DOC/SEC_VTX/CDFR/1922 (1992).
- [15] CDF Collaboration, The CDF upgrade, CDF/DOC/CDF/PUBLIC/3171
 (1995).
- [16] A. Affolder *et al.*, Construction report of the intermediate silicon layers
 (ISL) ladders, Nucl. Instrum. Methods Phys. Res., Sect. A 461 (1-3) (2001)
 216 218, 8th Pisa Meeting on Advanced Detectors.
- 1869 [17] Evonik Industries, Rohacell.
- 1870 URL http://www.rohacell.com
- ¹⁸⁷¹ [18] S. Holmes, R. S. Moore, V. Shiltsev, Overview of the Tevatron Collider ¹⁸⁷² Complex: Goals, Operations and Performance, JINST **6** (2011) T08001.
- [19] E.J. Thomson *et al.*, Online track processor for the CDF upgrade, IEEE
 Transanctions on Nuclear Science 49 (3) (2002) 1063 1070.
- 1875 [20] S. Belforte *et al.*, Silicon Vertex Tracker Technical Design Report,
 1876 CDF/DOC/TRIGGER/PUBLIC/3108 (April 1995).
- [21] B. Ashmanskas *et al.*, The CDF Silicon Vertex Trigger, Nucl. Instrum.
 Methods Phys. Res., Sect. A **518** (1-2) (2004) 532 536, Frontier Detectors for Frontier Physics: Proceeding.
- [22] J. Adelman *et al.*, The Silicon Vertex Trigger upgrade at CDF, Nucl. Instrum. Methods Phys. Res., Sect. A **572** (1) (2007) 361 364, Frontier
 Detectors for Frontier Physics, Proceedings of the 10th Pisa Meeting on
 Advanced Detectors.
- [24] M. Garcia-Sciveres *et al.*, The SVX3D integrated circuit for dead-timeless
 silicon strip readout, Nucl. Instrum. Methods Phys. Res., Sect. A 435 (1-2)
 (1999) 58 64.
- [25] D. Sjoegren *et al.*, Radiation Effects on The SVX3 Chip,
 CDF/DOC/SEC_VTX/PUBLIC/4461 (January 1998).
- [26] J. Andresen etal., Radiation Hardness of The Compact 1892 the CDF Silicon Tracking Card for Detector Upgrade, 1893 Port CDF/PUB/PRODUCTION/PUBLIC/5535 (January 2001). 1894

- [27] M.L. Chu *et al.*, Radiation hardness of the 1550-nm edge emitting laser for the optical links of the CDF silicon tracker, Nucl. Instrum. Phys. Methods Res., Sect A 541 (1-2) (2005) 208 – 212, Development and Application of Semiconductor Tracking Detectors: Proceedings of the 5th International Symposium on Development and Application of Semiconductor Tracking Detectors (STD 5).
- [28] VME International Trade Association, VME Standard.
 URL http://www.vita.com/
- ¹⁹⁰³ [29] Chu-Sun Yen *et al.*, G-Link: A Chipset for Gigabit-rate Data Communica-¹⁹⁰⁴ tion, Hewlett Packard Journal **43** (5) (1992) 103–115.
- [30] S. Nahn, M. Stanitzki, T. Maruyama, Silicon Resonance Detection Using
 the Ghostbuster Board, CDF/DOC/CDF/PUBLIC/7749 (August 2005).
- ¹⁹⁰⁷ [31] A. Abulencia *et al.*, Measurement of the $B_s^0 \overline{B}_s^0$ Oscillation Frequency, ¹⁹⁰⁸ Phys. Rev. Lett. **97** (2006) 062003.
- [32] R.J. Tesarek *et al.*, Radiation effects in CDF switching power supplies,
 CDF/DOC/CDF/PUBLIC/5903 (March 2002).
- [33] Siemens AG, Siemens 575 PLC.
 URL http://support.automation.siemens.com/
- [34] Siemens AG, Siemens Quadlog PLC.
 URL https://eb.automation.siemens.com/
- [35] G. E. Totten, D. S. Mackenzie (Eds.), Alloy Production and Materials
 Manufacturing, Vol. 2 of Handbook of Aluminium, CRC Press, Boca Raton,
 Florida, 2003.
- [36] 3M, Scotch DP190 Epoxy Adhesive.
 URL http://www.3m.com/
- [37] P. Dong *et al.*, Beam Condition Monitoring With Diamonds at CDF, IEEE
 Transactions on Nuclear Science 55 (1) (2008) 328 -332.
- ¹⁹²² [38] GE Fanuc, GE Intelligent Platforms.
- URL http://www.ge-ip.com/products/3311/
- [39] R.J. Tesarek *et al.*, A measurement of the radiation environment in the CDF tracking volume, Nucl. Instrum. Methods Phys. Res., Sect. A 514 (1-3) (2003) 188 193, Proceedings of the 4th International Conference on Radiation Effects on Semiconductor Materials, Detectors and Devices.
- ¹⁹²⁸ [40] M. Michael, Radiation damage in silicon particle detectors: Microscopic defects and macroscopic properties, Desy-thesis-1999-040 (1999).

- [41] V. Eremin, E. Verbitskaya, Z. Li, The origin of double peak electric field
 distribution in heavily irradiated silicon detectors, Nucl. Instrum. Methods
 Phys. Res., Sect. A 476 (2002) 556 564.
- [42] M. Swartz *et al.*, Observation, modeling, and temperature dependence of doubly peaked electric fields in irradiated silicon pixel sensors, Nucl. Instrum. Methods Phys. Res., Sect. A 565 (1) (2006) 212 – 220, PIXEL 2005: International Workshop on Semiconductor Pixel Detectors for Particles and Imaging.
- ¹⁹³⁸ [43] T. Aaltonen *et al.*, Evidence for $D^0 \overline{D}^0$ Mixing Using the CDF II Detector, ¹⁹³⁹ Phys. Rev. Lett. **100** (2008) 121802.
- [44] B. Brau, Operational experience with the CDF Run II silicon tracker, Nucl.
 Instrum. Methods Phys. Res., Sect. A 541 (1-2) (2005) 73 77, Proceedings
 of the 5th International Symposium on Development and Application of
 Semiconductor Tracking Detectors (STD 5).
- [45] D. Acosta *et al.*, Measurement of the $t\bar{t}$ production cross section in $p\bar{p}$ collisions at $\sqrt{s} = 1.96$ TeV using lepton + jets events with secondary vertex *b* -tagging, Phys. Rev. D **71** (2005) 052003.